AMERICAN MACHINIST INDEX

McGRAW-HILL PUBLISHING COMPANY, INC., 330 WEST 42ND STREET, NEW YORK 36, N. Y.

CONTENTS OF VOLUME 96 JANUARY TO DECEMBER, 1952

A

Abrasives:

Abrasive belts grind carbide. G. H. DeGroat ... Dec. 8—102
Belt grinding tapers wing skins. J. R. Burns ... Sept. 1—154
Evolution of modern abrasives ... Mid-Nov. section C4
How to grind titanium. Dr. L. P. Tarasov. (charts & tables) (report) ... Nov. 10—135-146
Planned abrasive control. (charts) C. R. Glenn ... June 23—102

Air compressors:

Air-cushion for heavy jigs. C. T. Bower (P.I.) ... Nov. 24—162
Don't neglect feed volume for air-operated devices. Fred Bertino (P.I.) ... Nov. 10—171
Hydraulics and pneumatics for machine tools ... Mid-Nov. section A19
Slowing up air-cylinder action. J. C. Salinas (P.I.) ... Mar. 3—180

Aircraft construction:

Aircraft rescheduling cuts back production 10% ... Sept. 15—182
B-36 order, cut back, replaced by new planes ... Dec. 22—133
Bell aircraft guided missiles: ingenious machines weld thin-wall stainless tanks. R. L. Brown ... Nov. 24—128
Belt grinding tapers wing skins. J. R. Burns ... Sept. 1—154
Campbell Report results in some quiet service scurrying ... Oct. 13—188
Ceramics shield stainless for jets at Stewart-Warner Corp. R. G. Hicks ... July 21—99
Chance-Vought Aircraft welding study: titanium and titanium-alloy sheet (tables) ... May 26—98
Chrome-glass coating on molybdenum for jet-engine parts ... Sept. 1—109
Contouring with heavy machine tools. Pt. 1 the dual-purpose machine tool. W. B. Wigton ... pt. 2 the amplidyne contouring drive. J. L. Dutcher ... Oct. 27—114
"Cumulative sampling" boosts shop output 22%. C. H. Latter ... Sept. 29—93
Die quenching precision forms tough alloys (tables). Corral & Boarts ... July 7—125
Douglas Aircraft's A3D for Navy passes first tests ... Dec. 8—152
First post-Korea planes ... June 9—177
GE cuts cost of making jet blades ... Mar. 3—201
"Hot copper sandwich" may boost jet performance ... June 9—157
How Curtiss-Wright extrudes propeller blades ... Apr. 28—143
Hot dimpling forms tough aircraft skin. John Starr ... Mar. 3—160
How we weld titanium. Rohr Aircraft Corp. T. R. Bradley ... Oct. 13—123
How wing skins for B-47 stratojets are taper-milled. Jerry Sanford ... Apr. 14—166
Jet metalsmiths (apprentices) learn the right way (the hard way) ... Sept. 15—182
Lockheed building Air Force's first turboprop cargo transport ... Nov. 10—191
Master fixtures: master assembly troubles at Consolidated Vultee Aircraft. Frank Charity ... Mar. 31—92
New jet manufacturing techniques shown ... Mar. 31—136
New stretch-forming techniques at North American Aviation. Frank Charity ... Sept. 1—113
Northrop Aircraft plant-layout checkerboard ... Dec. 8—161
Northrop's new scheduling plan for the sheet-metal shop. D. R. Huish ... July 7—157
Novel methods are weld high-strength alloys at Solar Aircraft. Harkins & Thompson ... Dec. 8—119
Picture prints speed assembly ... Aug. 4—128
Ryan Aeronautical Co. shop shots ... Aug. 4—103
Sandwich structures are simple ... May 26—118
75,000-ton forging press no longer considered vital to plane output ... Jan. 7—169
Sigma welding stars on 3 new jobs at Solar Aircraft. Frank Harkins ... Aug. 18—109
6 "shop kinks" boost output at Douglas Aircraft. W. A. Nordhoff ... Aug. 4—108
Sonic tester checks bonding of honeycomb panels at Douglas Aircraft. H. O. Williams ... Sept. 1—116
Special duplicators speed experimental jet-engine blades. M. J. Rowan ... Mar. 3—166
Specially designed fixture bends high-strength extruded shapes. F. C. Hoffman (report) ... July 21—115-122
Super "nerve center" cam for automatic control of aircraft in flight. J. W. Mallory ... Mar. 31—83
Temco Aircraft Corp. shop shots ... Apr. 28—100
Tool talk from Temco Aircraft Corp. ... Nov. 24—136
Turning a jet compressor frame (cover) ... Nov. 10—2
Turret lathes build turbojets ... Feb. 4—119
Upset welding die cuts job time 98% at Northrop Aircraft. E. A. DeVoss ... Oct. 13—160
Welding stars in aircraft production. F. S. Dever ... May 12—170

Aluminum:

Aluminum-alloy tubes from slugs: 125 extrusions per minute. Frank Charity ... May 26—100
Bliss welds heavy presses for aluminum forging program ... Sept. 29—147
Die quenching precision forms tough aluminum alloy. Corral & Boarts (tables) ... July 7—125
The growth of aluminum ... Mid-Nov. section A8
How aluminum bonding is keyed to production. W. M. Stocker Jr. ... July 21—108
How to roll back forming costs. A. F. Schuh ... Mar. 17—152
Packard's precision job-lot tooling makes high-speed diesels for the Navy. B. C. Brosheer ... Nov. 24—149
Three new producers get into field ... Dec. 22—136

American Gear Mfrs. Assn. annual meeting approves new gear standards ... June 23—140
Annual meeting prepares streamlined constitution ... Nov. 10—190

American Machine Tool Distributors Assn.
Stress problem of keeping machine-tool industry strong ... Apr. 28—142

American Machinist:

The first 75 years ... Mid-Nov. section L
Metalworking facts for 1952 (charts & tables) ... Jan. 21—129-144
Metalworking price index announced ... Mar. 31—132
1952 Production Preview ... Jan. 21—145-272
75th anniversary issue ... Mid-Nov. issue
Wholesale price indexes for machinery ... Mar. 3—202

American Machinist Special Reports:

Alco tooling assembles the M-47 hybird. E. J. Tangerman ... Aug. 18—119-126
Calculating form tools. J. H. Porsch ... Mar. 3—145-152
Curtiss-Wright boosts output with machinability data. Rupert LeGrand (report) (tables) ... Nov. 24—140-148
Don't overlook operator safety in press tool design. L. A. Faulkner ... Sept. 1—121-136
How Ford automates production lines. Rupert Le Grand ... Mar. 17—135-150
How Ford extends automaticity to engine handling. M. J. Rowan ... June 23—113-120
How modern gun-drilling improves bole-making. W. M. Stocker Jr. ... May 26—109-116
How Sperry harnesses the electron. E. J. Tangerman ... Apr. 14—143-157
How to apply metal to glass and ceramics. Samuel Wein ... July 7—147-154
How to bend high-strength extruded shapes. F. C. Hoffman ... July 21—115-122
How to cast constant-tolerance forming dies ... Feb. 4—111-118
How to cut overhead costs. D. E. McNeil (charts & tables) ... Sept. 29—111-122
How to grind titanium. Dr. L. P. Tarasov (charts & tables) ... Nov. 10—135-146
How to machine and finish stainless steel. Stevens, Bankoski & Spencer ... Aug. 4—111-126
How to maintain heat-treating equipment. T. A. Frischmann (tables) ... Oct. 13—135-146
How to run a drillpress. H. E. Linsley ... Feb. 18—147-162
How to run an engine lathe ... May 12—143
How to run a grinding machine. H. E. Linsley ... Oct. 27—125-140
How to tip tools with prehardened HSS. L. J. St. Clair ... Jan. 7—133-140
How to work with beryllium-copper strip (charts & tables) J. T. Richards ... Mar. 31—99-114
How and why taps are precision ground. S. W. Lovejoy ... June 9—135-142
Latest improvements in press automation at Ford. M. J. Rowan ... Dec. 8—109-118
Men of "parts" watch machines work at Sylvania-Tangerman & De Groat ... Sept. 15—113-136
Noise . . . a shop problem ... Dec. 22—109-116
Plasticale prototypes speed Ford tooling. Rupert LeGrand ... May 12—159-164
Plastics—equipment and technique. D. A. Dearle ... Apr. 28—107-122
Shop pensioners disprove the rules ... Apr. 14—162-164

American Ordnance Assn. Symposium clears defense aims ... Dec. 22—135

American Society for Testing Materials Survey shows greater productivity, simpler controls needed ... Jan. 21—290

American Society of Mechanical Engineers Centennial of Engineering attracts International Society attention ... Sept. 29—146
73rd annual meeting elects officers, covers machine tools, presses, handling ... Dec. 22—134

American Society of Tool Engineers Foreign machines dominate tool show ... Mar. 31—133
1952 Industrial Exposition floor plan ... Mar. 3—206
1952 Industrial Exposition list of exhibitors ... Mar. 3—208
Survey shows better machine tools needed ... Jan. 7—166
Tool Show—new parts and equipment ... Mar. 3—210

American Standards Association Standards work awards to Batt & Hoagland ... Dec. 8—161

Ametoot—travel group of 33 Japanese complete visits to U. S. metalworking shops ... Dec. 22—137

Angles:

Calculating form tools. J. H. Porsch ... Mar. 3—145-152
Compound angles simplified. R. G. Vare (P.I.) ... Feb. 4—133
High rake angles aid milling performance. Crawford & Merchant ... July 7—172
Sine bar with lever corrects compound angles. R. G. Vare (P.I.) ... Mar. 17—155

Arbors—Arbor collars assemble without disassembly. Robert Laimbeck (P.I.) ... Apr. 28—125
Simplified arbor collars. A. Vetsch (P.I.) ... July 21—137
Arm with mechanical muscle ... Nov. 24—129

Arsenals—General Ford tells the ordnance story ... Aug. 18—146
Assembly machines and conveyors ... Mid-Nov. section F9

Atomic Energy Commission—How Oak Ridge machines beryllium. Cane & Watkins ... Dec. 22—93

Automation:

Air and ideas make spotwelder automatic. R. P. Roberts ... Dec. 22—104
Automatic handling and automatic machine operation triple pail-line output. E. F. Paquette ... Dec. 22—98
Developments in automation ... Mid-Nov. section C12
Dodge automates press forging. Rupert LeGrand ... Sept. 29—123
How Ford automates production lines. Rupert LeGrand ... Mar. 17—135-150
Latest improvements in press automation at Ford. M. J. Rowan (report) ... Dec. 8—109-118
Retriever unloads diecaster automatically. R. E. Fromson ... Dec. 22—100

Automobile Construction:

How Ford automates production lines. Rupert LeGrand ... Mar. 17—135-150
How Ford extends automaticity to engine handling. M. J. Rowan ... June 23—113-120
How Studebaker makes a crankshaft. Foreman & Mishler ... Mar. 3—156
Letter from Germany. Burnham Finney ... Oct. 27—107
Plastic die forms truck-cowl for Chrysler ... Sept. 29—144
Plasticale prototypes speed Ford tooling. Rupert Le Grand (report) ... May 21—159-164

(ed) Editorial (P.I.) Practical Ideas

B

Balancing—How to balance a machine without an expert with electronic vibration indicator. May 12—173
Magnets find balance on flywheels. A. H. Poole (P.I.) July 21—127
Bare Argon arc welds copper bus bars. W. A. Brauer Jr. May 12—174

Bearings:

Ball-bearing stock guide. J. F. Sheppersack (P.I.) Sept. 15—165
Ball grippers retain work on tapered turning mandrel. Craig Kerr (P.I.) July 7—160
Carbide bar at 90,000 rpm finishes exact Rc63 bores. E. J. Tangerman. Mar. 3—142
Gravity bearings support idler gear. R. Mery (P.I.) July 21—127

Belting:

Abrasive belts grind carbide. G. H. DeGroat Dec. 8—102
Belt grinding tapers wing skins. J. R. Burns Sept. 1—134
Tapered punch cuts holes in belting. D. D. Amison (P.I.) Aug. 18—132

Bending:

Adjustable cams time bending. G. H. DeGroat June 9—155
Ball-bearing fixture bends plates. G. C. Best (P.I.) Mar. 31—118
Bending and flanging in one operation cuts job time 98%. E. A. DeVoss Oct. 13—160
Big bends make farm-loader booms. B. C. Brosheer June 23—108
Cold bending a boom (cover) June 23— 2
Correct curves for carbides May 12—142
Double-bending die set forms small channels. H. Hahl (P.I.) Aug. 4—131
Hand bending tools make roller-bearing brackets. D. L. Vance (P.I.) Apr. 28—128
How to bend high-strength extruded shapes. F. C. Huffman (report) July 21—115-122
Multiple bending multiplies production. T. M. Rybarczyk Feb. 4—100
Planer fixture bends bolts. Stanley Hodges (P.I.) Mar. 31—120
Rotating punch bends small rings. Hjalmar Dahl (P.I.) June 9—164

Beryllium—How Oak Ridge machines beryllium. Case & Watkins Dec. 22— 93
How to work with beryllium-copper strip. J. T. Richards (charts & tables) Mar. 31—99-114

Blanks—Rod collects punched blanks. Haim Murro Nov. 10—173

Blasting—Wet blasting before and after plating of tools eliminates regrinding and blasting Oct. 13—158

Blocks:

Angle blocks made for quick setups. R. H. Fry (P.I.) May 12—177
Ball-bearing V-blocks set up shafts and bars. R. R. Calhoun Jr. (P.I.) May 12—180
Button block does precise hole locating. J. C. Magee (P.I.) July 21—129
Die biller blocks support thin punch wall. F. C. Elmo (P.I.) July 21—128
Edge locating block speeds jig-borer setup. Sam Winston (P.I.) Dec. 22—122
Graphite blocks trepanned to save $20 each. Edward Walker Nov. 10—122
Setup blocks works on lathe or grinder. Sam Winston (P.I.) July 21—129
Simple stepped parallel blocks. C. T. Bower (P.I.) Oct. 27—147

Bolts:

Accessories for OBI presses (Ref. Bk. Sheets) Oct. 13—179
Bolt-steel classification (tables) (Ref. Bk. Sheets) Apr. 14—187
How to tighten hidden bolts. S. V. Worth (P.I.) Oct. 13—170
Progress in bolts and screws Mid-Nov. section F7

Bonding—How aluminum bonding is keyed to production. W. M. Stocker Jr. July 21—108

Boring and Boring Machines:

Adjustable boring bar swivels on set screws. J. C. Salinas (P.I.) Mar. 3—176
Boring bar brace. A. W. Buckles (P.I.) June 9—164
Boring bar brace allows quick adjustment. Louis Meyer (P.I.) Aug. 4—129
Boring internal clearance. John Stewart (P.I.) Oct. 13—172
Boring mill cam follower improves finish, cut time. W. S. Ball (P.I.) May 12—176
Boring tools made from old drills, reamers. G. J. Van Hecke (P.I.) Mar. 17—157
Carbide boring tool for deep holes. Allan Clarke Nov. 10—171
Carbide bar at 90,000 rpm finishes exact Rc63 bores. E. J. Tangerman Mar. 3—142
Compound curve machined on boring mill. C. D. MacKinnon (P.I.) May 26—122
Convenient clamp for boring bar backface. A. Clarke (P.I.) Sept. 29—134
Converted lathe bores ball sockets. C. D. Mackinnon (P.I.) Aug. 18—131
Counterbore for plastics. Bernard Levowich (P.I.) Mar. 31—119
Dual-purpose boring mill (cover) Oct. 27— 2
Eccentric boring head. C. Y. Lee (P.I.) Sept. 15—164
Edge locating block speeds jig-borer setup. Sam Winston (P.I.) Dec. 22—122
Faceplate stops speed boring work. Lauri Ayala (P.I.) Apr. 14—178
Gear-centering device locates shafts for boring. J. McDonald (P.I.) May 26—123
How to grind boring tools. E. J. Kaiser (Ref. Bk. Sheets) Pts 1 & 2 Mar. 31—125
Internal grinding a large bore. B. L. Adamson (P.I.) Nov. 24—163
Jig bores two holes at once. Hjalmar Dahl (P.I.) Dec. 8—142
Lathe doubles as boring mill. Lewis Cranston Nov. 24—156
Line-boring tailstock. C. Y. Lee (P.I.) Sept. 15—163
Offset boring tool rotates to cut. Lyle Vinger (P.I.) June 9—161
Outboard spindle bores oversize plate. William Lipowski (P.I.) Jan. 7—153
Pipe makes rugged boring bar. J. F. McCafferty (P.I.) Nov. 24—161
Radial spacing beyond normal jig-borer limits. Dietlin & Steven (P.I.) Dec. 22—123
Rebuilding a boring machine pays off. Paul Jordan Jan. 7—142
Round cutter machines counterbores. W. M. Halliday (P.I.) July 7—162
Small carbide boring bits work better than large ones. N. Palmer (P.I.) June 23—128
Smart tooling solves tough elliptical boring job. S. D. Phillips Dec. 8—140
Souped-up tooling does double-decker turning. C. W. Hesse Jan. 7—141
Surplus borer tooled for spheres. Paul Jordan Feb. 4—110
Turning and boring developments Mid-Nov. section E11
Turret mirrors save steps in deep-hole boring. Hadley Jacobs (P.I.) May 12—176

Boxes—Converting skid boxes for long stocks. H. G. Frommer (P.I.) Mar. 31—122
Standard roller-turning box modified to spin tube ends. Allen Clarke (P.I.) May 12—178

Brackets—Bracket locks without marring shaft. L. Kasper (P.I.) July 21—127
Hand bending tools make roller-bearing brackets. D. L. Vance (P.I.) Apr. 28—128

Brass—Flame-fluxing with brass brazes high-strength assemblies. John Shinn Nov. 24—133
How to understand brass. Samuel Storchheim Oct. 13—151

Brazil—Point 4 program will expand industry there Dec. 8—161

Brazing:

Brazing flux causes spatter. J. M. Dyson (P.I.) Apr. 28—126
Continuous preforms for faster brazing May 26—105
Flame-fluxing brazes high-strength assemblies. John Shinn Nov. 24—133
How to tip tools with rebardened HSS. L. J. St. Clair Jan. 7—133-140
How to work with beryllium-copper strip. J. T. Richards (charts & tables) Mar. 31—99-114
Inconel brazed in hydrogen at Sylvania (cover) July 21— 2
Induction brazes squirrel cage. Brace & Fitzgerald Mar. 17—124
Induction brazes squirrel cage at Westinghouse (cover) Mar. 17— 2
Induction brazing can be used for copper and copper-alloy parts. E. M. Laughner Nov. 24—138

Briquetting—an non-powder cam block. G. H. DeGroat Sept. 1—105

Broaching and Broaching Machines:

Broaching makes an anchor. J. A. Peenka Apr. 14—140
Broaching today Mid-Nov. section E20
Drill jig eases square-hole broaching. Chris Sorenson (P.I.) Feb. 18—170
Drilling holes for rough broaching. A. Vetsch (P.I.) May 26—120
Keyway tools added to regular broaches. A. Vetsch (P.I.) Jan. 7—153
Microbroaching . . . new technique for tiny, odd-shaped holes. J. S. Dennison Mar. 3—134
"Strip" broaching boosts output. C. W. Kalb Apr. 28—124
Toothing a turret ring gear at Detroit Tank Arsenal (cover) Mar. 3— 2
Two-station broaching die has inverted stripper plate. Anthony Gabriele (P.I.) Feb. 4—134

Burring—Carbide bar at 90,000 rpm finishes exact Rc63 bores. E. J. Tangerman Mar. 3—142

Bushings—Drill bushings act as clamps. Cliff Bussmann (P.I.) Oct. 27—148

(ed) Editorial (P.I.) Practical Ideas

C

Calipers—Measure hidden diameters. J. G. Bradley (P.I.) Oct. 27—144

Cams:

Adjustable cams time bending. G. H. DeGroat June 9—155
Boring-mill cam follower improves finish, cuts time. W. S. Ball (P.I.) May 12—176
Cam clamp clears work quickly. Tom Brown (P.I.) May 12—179
Cam for jig clamping. R. Mery (P.I.) Dec. 8—145
Cam-latch speeds steadyrest loading. O. O. Kilbourn (P.I.) Sept. 15—166
Cam lock in mandrel prevents slip. Del Hansen July 7—137
Cams drive small cores in an injection mold. G. H. DeGroat June 23—110
Super "nerve center" cam. J. W. Mallory Mar. 31— 83
This 3-dimensional control cam costs $2800 (cover) Mar. 31— 2
Turret slide and miller cut cams. Allan Clarke (P.I.) Mar. 17—154

Canadian General Electric—shop shots Mar. 17—134

Carbides:

Abrasive belts grind carbide. G. H. DeGroat Dec. 8—102
Carbide boring tool for deep holes. Allan Clarke Nov. 10—171
Carbide bar at 90,000 rpm finishes exact Rc63 bores. E. J. Tangerman. Mar. 3—142
Carbide insert stops swing-stop wear. O. V. Howe (P.I.) Sept. 1—143
Carbide inserts take clutch-collar wear Feb. 4— 99
Carbide toolbit reground only on top. J. M. Askin (P.I.) Mar. 17—155
CO_2 cools carbide grinders. A. B. Albrecht (table) Dec. 8— 97
Correct curves for carbides May 12—142
Cost of grinding carbide. H. W. Wagner (Ref. Bk. Sheets) (tables) Apr. 14—183
Curtiss-Wright boosts output, cuts costs, with machinability data. Rupert Le Grand (report) (tables) Nov. 24—141-148
Electrolytic grinding cuts carbides Oct. 13—189
Electrolytic grinding of carbide tools. Metzger & Keelerie Nov. 10—154
Europe studies carbide cutting. E. J. Tangerman Feb. 18—134
Grooving cutter uses carbide toolbits. Stanley Kusmer (P.I.) Dec. 8—146
How to conserve carbides. J. S. Gillespie (Ref. Bk. Sheets) Pts 1, 2 & 3 Jan. 21—275
How to machine stainless steel with carbides. J. J. Robert Oct. 27—109
Negative rake helps carbide core drills. W. F. Clark (P.I.) Apr. 28—130
Preformed shapes save time and carbide. Fischer & Pflug Apr. 28—104
Small carbide boring bits work better than large ones. N. Palmer (P.I.) June 23—128
Soft steel and ultrasonics machine carbide. G. H. DeGroat Sept. 15—141
Tool-shank sizes for carbides. M. F. Judkins Feb. 18—268

Carbon—Relation of combined to graphitic carbon affects machinability of gray irons. Lorig, Boulger & Shaw (charts) Oct. 27—122

Castings:

Disk grinder conveyor mass-finishes raw castings. J. F. Budnick (P.I.) July 21—126
Flame hardening mechanite castings. Dr. C. R. Austin (tables) May 12—165
How to cast constant-tolerances forming dies Feb. 4 *111-118
How to make zinc-alloy drop-hammer dies. Pts 1, 2, 3 (Ref. Bk. Sheets) Feb. 4 *137
How to seal porous castings. M. J. Nathanson Pts 1 & 2 (Ref. Bk. Sheets) Jan. 7—161
Investment castings need not be "free-machining" stainless. Wood & Von Ludwig (charts & tables) Nov. 10—147
New investment foundry features latest techniques. Mat. J. T. Andrews Jr. Jan. 7—128
Repair of iron castings (Ref. Bk. Sheets) Pts 1, 2 & 3 Sept. 29—137
Pts 4, 5 & 6 Oct. 13—175
Retriever unloads diecaster automatically. R. E. Fromson Dec. 22—100
Scribing circles on castings. L. J. Pech (P.I.) Apr. 14—180
Skilled investment castings. D. F. B. Teddis July 7—141
What's ahead the next ten years in casting and molding Mid-Nov. section B

Centering:

Ball-bearing tube center. H. Woerle (P.I.) Oct. 27—145
Boring-bar hole gage centers automatically. A. Vetsch (P.I.) Apr. 14—179
Centering drill jig grips parts securely. J. G. Decker (P.I.) Aug. 4—129

Gear-centering device locates shafts for boring. J. McDonald (P.I.) May 26—123
Grinding centers for hardened parts. Neville Palmer (P.I.) Dec. 8—145
Reamer-centering collar improves accuracy. O. W. Anderson (P.I.) Feb. 18—166
Ring chucker center automatically. W. M. Halliday (P.I.) Apr. 14—178
Spindle adapter for lathe centers small-size bars. Paul Jeannet (P.I.) June 9—162
Spring headstock center increases shouldering accuracy. I. J. Peacock (P.I.) May 26—123
Tailstock center for old lathe is spring-loaded. Pierre Wilmus (P.I.) Mar. 17—158
Torsion spring used on centering device. Haim Murro (P.I.) Nov. 10—171
Two- equalizing locating methods. N. Palmer (P.I.) May 26—121

Chips:
Full conveyorization eliminates manual chip-handling. D. C. Peterson Oct. 13—162
How Ford plans for low-cost chip handling. M. J. Rowan Apr. 14—134
Tool engineers influence "producibility"—elimination of chips June 23—140
Turret chip breaker clamps next to tool. J. C. Salinas (P.I.) Mar. 31—122

Chucks and Chucking Machines:
Back-up bars for chucking. C. T. Bower (P.I.) Oct. 13—171
Crane and sling changes chucks. W. L. Perry (P.I.) Apr. 28—128
Drillpress fixture has chuck on table. Robert Roedder (P.I.) Feb. 18—167
Expanding mandrel works with chuck. M. Sgt. J. K. Wood (P.I.) Aug. 4—134
Flexing chuck jaws grip castings accurately. J. G. Decker (P.I.) June 23—127
Four jaws work fast as three. R. W. Morrison (P.I.) Sept. 1—142
Grinding wheel on lathe trims up chuck jaws. I. J. Peacock (P.I.) Mar. 3—178
Low-voltage magnetic holding for milling on magnetic chucks. Axel Anderson May 12—127
Mandrel on sliding-jaw chuck grips work on the ID. Allan Clarke (P.I.) Feb. 4—134
Modified tapping head chucks odd pieces. Allan Clarke (P.I.) Mar. 3—178
Multi-jaw chuck adapted for holding off-shapes. R. G. Varse (P.I.) Mar. 17—158
Ring chucker centers automatically. W. M. Halliday (P.I.) Apr. 14—178
Shell-chucking fixture speeds turning operations. D. G. Nolle (P.I.) Apr. 28—125
Slab chuck grips parts by vacuum. Mar. 17—123
Solid parallels on chuck. B. E. Long, Jr. (P.I.) Sept. 29—131
Truing chuck jaws. R. H. Fry (P.I.) Mar. 31—121
Two chucking faceplates hold work on center. N. Palmer (P.I.) June 23—125

Clamps:
Adjustable clamp works with leaves. Haim Murro (P.I.) Apr. 28—128
Cable clamping jig. Irving Epstein (P.I.) Oct. 27—145
Cam clamp clears work quickly. Tom Brown (P.I.) May 12—179
Cam for jig clamping. R. Mery (P.I.) Dec. 8—145
Clamping lathe dog acts quickly. K. Matsumoto (P.I.) Jan. 7—152
Convenient clamp for boring bar back-facer. A. Clarke (P.I.) Sept. 29—134
Double equalizing clamp grips twin parts. Edward Walker (P.I.) Aug. 4—133
Drill bushings act as clamps. Cliff Bossman (P.I.) Oct. 27—148
Equalizing clamp for pressework. F. C. Elmo (P.I.) Nov. 10—172
Expanding fixture grips round collars. N. F. Kfoury (P.I.) July 7—158
Flat bar clamps versatile workholders. C. H. Willey (P.I.) Dec. 22—122
Half screw clamps jaws rapidly. R. J. Dodson (P.I.) July 21—128
Hinge clamp grips side of work. N. Pearson (P.I.) Feb. 4—133
Holding blocks do a tough fixturing job. S. K. Rudorf Jan. 7—150
Improved clamp stops marred work. C. Coy (P.I.) Dec. 22—120
Lever clamp eliminates half-turn screw. R. Mery (P.I.) Sept. 1—140
Maintain alignment in small sectional dies. Federico Strasser (P.I.) Dec. 8—143
Nut-clamp grips screws for cut-off. C. T. Bower (P.I.) Sept. 29—132
Off-center V-roller clamps odd-shaped part. Jack Jensen (P.I.) Mar. 3—179
Partly threaded strap has clamping flexibility. Allan Clarke (P.I.) July 21—126
Planer and shaper clamp for thin-sheet machining. C. T. Bower (P.I.) May 12—175
Screw-clamped fixture has fast action. Tom Brown (P.I.) Mar. 17—154
Simple clamps speed tooling. Neville Palmer (P.I.) Oct. 27—144
Springs added to fixture to get downward clamping. J. W. Bowler (P.I.) Feb. 4—132
Stop jaw creep on cam-lock vise. J. C. Magee (P.I.) Sept. 15—166
Swivelling clamp arm has fast action. Edward Walker (P.I.) Mar. 31—118
Universal clamp adjusts for any height. Hialmar Dahl (P.I.) Apr. 14—179
Welding clamps hold beams and irons. Robert Lambsock (P.I.) May 12—177
Welding clamps locate and grip. Alwyn Ward (P.I.) May 12—178
What clamping force? S. Tilles (Ref. Bk. Sheets) (table) June 23—131
Wooden soldering clamps set up corners. C. T. Bower (P.I.) Sept. 1—141
Cleaning—Solar Aircraft's "doghouse" pens up plant housekeeping Sept. 15—160

Coatings:
Ceramics shield stainless for jets. R. G. Hicks July 21— 99
Chemical treatment. Mid-Nov. section H— 7
How to apply metal to glass and ceramics. Samuel Wein July 7—147-154
Organic coatings. Mid-Nov. section H— 2
Solid-film lubricant finish applied by Friden Calculating Machine. Fred Shear Sept. 29—128
Temperature-resistant ceramic coatings make furnace fixtures last longer. D. K. Kroesch July 21—101
Coils—Stretching electric resistance coils. Haim Murro (P.I.) Nov. 24—164
Strip-coiling fixture makes heat exchangers. Bario Baltuch (P.I.) July 7—159
Coining—Coining controls thickness and location of shell flange. May 26—106
Collets—Double-action die forms, pierces, pronged collets. B. Menkin (P.I.) Nov. 10—174
Special broached collet holds two sizes. B. A. Rogers. (P.I.) July 21—130
Collimator—how to use it. R. F. Mitchell Nov. 10—161
Compass—Quick-acting beam compass. Mordechai Montag (P.I.) Oct. 27—146

Contour Machining:
Contouring with heavy machine tools. Pt. 1 the dual-purpose machine tool W. B. Wigton Pt. 2 the amplidyne contouring drive. J. L. Dutcher Oct. 27—114
Great grandpa did contour turning. Reed & Tweddle Nov. 10—119
Precision contour grinding makes better tools. F. C. Victory Pt. 1 Sept. 15—154 Pt. 2 Sept. 29—106
Scroll-cutting lathe rig. Allan Clarke (P.I.) Jan. 7—153

Contracts:
Charge small defense contractors forced to accept heavy losses. Apr. 28—140
Decision of NLRB may lead to union influence on subcontractors. Dec. 8—163
100 largest military prime contractors in 18 months since Korea. (table) June 9—183
Plan your government contracts for profits. Tomicki & Gunzel Jan. 21—298
Subcontracting news Jan. 7—215, Jan. 21—333 Feb. 4—195, Feb. 18—229, Mar. 3—281, Mar. 17—219, Mar. 31—185, Apr. 14—239, Apr. 28—191, May 12—197, May 26—139, June 9—182, June 23—145, July 7—183, July 21—147, Aug. 4—152, Aug. 18—156, Sept. 1—160, Sept. 15—184, Sept. 29—149, Oct. 27—162, Nov. 10—191, Nov. 24—181

Controlled Materials Plan:
Controls will probably end next January. Mar. 17—168
Decontrol near for materials, wages and prices. May 12—190
Mobilizers look for replacement. Sept. 15—180

Controllers:
The amplidyne contouring drive. J. L. Dutcher Oct. 27—117
Coil-winder speed nut has lever control. William Richter (P.I.) Apr. 14—178
Fiber ducts save time in wiring machine panels. R. T. Johnstone Dec. 8—105
Pushbuttons operate welder. Leo Braun Feb. 18—146
Remote throttle control built cheaply, installed quickly. Irving Epstein (P.I.) Aug. 4—132
Super "nerve center" cam. J. W. Mallory Mar. 31— 83
Switch adjustment controls timing. Louis del. Berg (P.I.) May 12—175
This 3-dimensional control cam costs $2800. (cover) Mar. 31— 2

Conveyors:
Automatics roll off the line. E. J. Tangerman Sept. 15—137
Automation triples pail-line output. E. F. Paquette Dec. 22— 98
Chip conveyors cut job-shop downtime. M. J. Rowan Feb. 4—104
Developments in conveyors. Mid-Nov. section J— 15
Disk grinder conveyor mass-finishes raw castings. J. F. Bednick (P.I.) July 21—126
Full conveyorization eliminates manual chip handling. D. C. Peterson Oct. 13—162
How Ford extends automaticity to engine handling. M. J. Rowan June 23—113—120
Retriever and conveyor unload diecaster automatically. R. E. Fromson Dec. 22—100
Stacked conveyors boost pressline flexibility George Corsi June 9—132
Transfer cars keep assembly moving. E. L. Brainard Nov. 10—132

Coolants—see Cutting Fluids
Counters—Part counting stand. Ferd Lettino (P.I.) Dec. 8—142

Copper:
Bigger allocations to benefit small users. Apr. 14—190
Copper alloys in metalworking. Mid-Nov. section A— 6
Half-hour test finds copper in steel. June 23—112
How to work with beryllium-copper strip. J. T. Richards (charts & tables) Mar. 31— 99—114
Induction brazing can be used for copper and copper-alloy parts. E. M. Laughner Nov. 24—138
Corrosion—Chemical treatment. Mid-Nov. section H— 7
Discourage corrosion through dry air. G. L. Simpson June 9—127
Corrosion—see also Rust Preventive
Cosmotron 'doughnut' magnet is 288 shop-made sandwiches Nov. 10—128

Costs:
Curtiss-Wright boosts output, cuts costs, with machinability data. Rupert Le-Grand (report) (tables) Nov. 24—141-148
Graphite blocks trepanned to save $20 each. Edward Walker Nov. 10—122
How to cut overhead costs. D. E. McNeil (charts & tables) (reports) Sept. 29—111-122
How to roll back forming costs. A. F. Schub Mar. 17—152
How to shear to closer limits. J. Murphy May 26—102
Induction brazing can be used for copper and copper-alloy parts. E. M. Laughner Nov. 24—138
Labor is the big factor in friction-sawing costs. Sept. 15—153
Nibbling die slides away from high costs. F. E. Wilson Aug. 18—129
On European competition. Burnham Finney Oct. 13—117
Planned abrasive control. C. R. Glenn (charts) June 23—102
Plant-wide planning stretches new-equipment dollars. M. J. Rowan Mar. 17—119
Round bar stock makes inexpensive machine slides. C. T. Bower (P.I.) Aug. 4—130
Standardized die blocks cut tool costs. J. S. Adams Mar. 31— 87
Tricky tooling stamps on stamping costs. M. J. Rowan Feb. 18—138

Cranes—Cranes, hoists, and monorails. Mid-Nov. section J— 10
Inspection gantry provides high reference surface. R. H. Fry (P.I.) July 7—158

Cutters and Cutting Machines:
Arc machining makes hard-to-cut jobs easy. Harding & Matulaitis Mar. 3—136
Compound curve machined on boring mill. C. D. MacKinnon (P.I.) May 26—122
Curtiss-Wright boosts output, cuts cost, with machinability data. Rupert LeGrand (report) (tables) Nov. 24—141—148
Cutter-grinder arbor adjusts for grinds. H. R. Gillham (P.I.) June 23—126
Cutting off. Mid-Nov. section E— 23
Dam tooling turns out tough steel rollers and tracks. Hilton & Shields Nov. 24—130
Dynamometer changes "art of metal cutting" to "science of metal cutting" E. J. Tangerman Oct. 13—139
Electrolytic grinding cuts carbides. Oct. 13—189
Europe studies carbide cutting. E. J. Tangerman Feb. 18—134
Grooving cutter uses carbide toolbits. Stanley Kusmer (P.I.) Dec. 8—146
High rake angles aid milling performance. Crawford B. Merchant July 7—172
How to cut gears without a dividing head. B. A. Rogers (P.I.) Apr. 28—126
How to run a drillpress—report. H. E. Linsley Feb. 18—147-162
Interchangeable mandrels to cut hobbing costs. Del Hansen May 12—138
Make research data useful to the shop man Dr. M. Kronenberg (tables) Sept. 15—145
Making special cutters for oddmilling jobs. L. B. Williams (P.I.) Aug. 4—133
Offset boring tool rotates to cut. Lyle Vinger (P.I.) June 9—161
Pneumatic angle drill cuts bearing grooves. S. H. Pearson (P.I.) Mar.31—120

(ed) Editorial (P.I.) Practical Ideas

Progressive radius milled by key shaft guided cutter. Eugene Winkler (P.I.) Nov. 10—170
Round cutter machines counterbores. W. M. Halliday (P.I.) July 7—162
Shaper swivel and tool cut radii and curves. A. T. Benson (P.I.) May 12—180
Shaving cutter slices brass to width. K. J. Dodson (P.I.) Sept. 1—141
Simple tool cuts hidden chamfer. R. J. Rossi (P.I.) Dec. 8—143
Sine bar with lever corrects compound angles. R. G. Vare (P.I.) Mar. 17—133
Springs load cutter that follows templet. R. G. Vare (P.I.) June 9—161
The story behind COs coolant. P. E. Bromberg Mar. 3—130
Tool backup braces bit. F. M. Buttrick (P.I.) Mar. 26—122
Tool-shank sizes for carbides. M. F. Jaffkins Feb. 18—168
Wide index plate finger compensates for cutter width. Robert Roehler (P.I.) July 7—159

Cutting Fluids:
COs cools carbide grinders. A. B. Albrecht (table) Dec. 8—97
COs cools tools. E. J. Tangerman Mar. 3—129
How Ford plans for low-cost chip handling and coolant purification. M. J. Rowan (charts) Apr. 14—134
How to cool oil-quench tanks. C. L. Ringquist Aug. 18—196
How to run a drillpress—report. H. E. Linsley Feb. 18—147-162
How to select a cutting fluid. Thomas Badger Sept. 1—118
Little high-pressure jets from below cool cutting edges better. R. J. S. Pigott Jan. 21—281
The story behind COs coolant. P. E. Bromberg Mar. 3—130
Unchlorinated water-soluble coolant. G. F. Lambert (P.I.) June 23—127

D

Defense:
Alco tooling assemblies the M-47 hybrid. E. J. Tangerman (report) Aug. 18—119-126
Bullard Story—management reveals unusual measures taken to meet defense requirements Apr. 14—192
Cartridge cases are drawn from hot forged cups. G. H. DeGroat Sept. 15—181
Charge small defense contractors forced to accept heavy losses Apr. 28—140
Congressional exasperation forces munitions-board shakeup Sept. 1—157
Defense "corporations" may get U.S. operations into black Sept. 15—178
Defense department check writing keeps climbing fast Aug. 4—148
Defense policy that makes sense. Burnham Finney Sept. 1—103
Delay in delivery of goods causes drop in government spending for '53. July 7—177
Establishment of Production Equipment Advisory Committee in Office of Defense Mobilization May 26—134
Heavy defense volume pushes tool and die shop expansion in Los Angeles Feb. 18—184
Industrial security put up to worker Sept. 1—156
Line welding speeds new armored hulls Oct. 27—150
Munitions-board symposium clears defense aims Dec. 22—133
Never underestimate the power of ... Burnham Finney Aug. 4—93
Offshore aid gets rolling with France awarded largest share Nov. 10—190
Plans of new Production Equipment Committee will influence defense budget June 9—176
Sensible plan for guns and butter. Burnham Finney Mar. 31—81
Steel strike impact on defense work snowballs as reserves dry up Aug. 4—144
U.S. buying abroad for NATO swings into high gear Aug. 4—143
U.S. will buy plates, parts in Europe for NATO forces June 23—118
What *stretch-out* means. Burnham Finney June 23—93

Defense Production Administration:
Biggest allocations of steel, copper, aluminum to benefit small users. Apr. 14—190
C-E-O-ell Report results in some quiet service scrapping Oct. 13—188
M.-machine-tool industries get 30% of Small Defense Plants Administration aid Oct. 27—188
Standardization demand throws Air Force and Navy into a tizzy. Aug. 4—149
Dehumidifiers Discourage corrosion through dry air. G. L. Simpson Dec. 8—147
Depreciation—Write-offs should be optional. Burnham Finney Apr. 14—175

Design:
Before you improve materials handling, ask yourself is this trip necessary. C. W. Metter June 9—143
Calculating form tools. J. H. Porsch Mar. 3—145-152
Don't overlook operator safety in press-tool design. L. A. Faulkner (report) Sept. 1—121-136
Hints for gage design. (Ref. Bk. Sheets) Pts. 1, 2 & 3 Mar. 3—195
How to design and apply master gears. Fred Bohle (charts & tables) Dec. 8—123
How to design diamond pin locators. F. J. LaBroad (chart) Dec. 8—108
Plastic equipment and technique. D. A. Dearle (report) Apr. 28—107-122
What redesign will do. (ed) Mar. 17—117

Diamonds, Industrial:
Drive on to conserve industrial diamonds May 12—190
Expansion due for cobalt and diamonds Dec. 22—136
How to conserve diamond wheels. E. T. Larson (Ref. Bk. Sheets) Pts. 1 & 2 Feb. 18—173
How to design diamond pin locators. F. J. LaBroad (chart) Dec. 8—108
Look at your diamond wheel dressers. George Daskel Jr. Oct. 27—142
New processes ... will machine the "unmachinable" (table) Mar. 17—130
Why and how we must conserve diamond dust? Anderson Ashburn Nov. 10—151

Dies:
Clamping die forms round springs. T. H. Hsu (P.I.) July 21—127
Composite dies blank, pierce, and form multiple parts. W. M. Stocker Jr. July 21—104
Corrective steps for blanking dies. Federico Strasser (P.I.) Dec. 22—122
Die filler blocks support thin punch wall. F. C. Elmo (P.I.) July 21—128
Die forms recess in drawn steel pot. E. Springthrope (P.I.) July 7—160
Die inserts increase life, improve work quality (P.I.) June 9—166
Die-maker's folding square. E. Diskavich (P.I.) Oct. 27—146
Diemakers' kinks. Federico Strasser Mar. 3—144, Mar. 17—133, Mar. 31—86, Apr. 14—131, Apr. 28—99, May 26—97, June 9—154, June 23—109, Aug. 18—111, Sept. 1—115, Oct. 13—127, Dec. 22—103
Don't overlook operator safety in press-tool design. L. A. Faulkner (report) Sept. 1—121-136
Double-action die forms, pierces, pronged collets. B. Menkin (P.I.) Nov. 10—174
Double bending die set forms small channels. H. Hahl (P.I.) Aug. 4—131
Double blanking forms sharp teeth in press job. Federico Strasser (P.I.) July 7—160
Follow these 22 steps in die setting. Federico Strasser Oct. 13—128
Grinding fixture aids die manufacture. Rupert LeGrand Nov. 24—134
Homemade floating diehead. C. Y. Lee (P.I.) Sept. 15—163
How to cost constant-tolerance forming dies Feb. 4—111-118
How to make zinc-alloy drop-hammer dies. (Ref. Bk. Sheets) Pts. 1, 2 & 3 Feb. 4—137
Jackscrew die-lifter. M. M. McKenzie (P.I.) Sept. 1—142
Knurling (Ref. Bk. Sheets) Pts. 1, 2 & 3 (tables) Dec. 22—127
Low-cost methods speed zinc, plastic and steel die construction. W. C. Miller Dec. 8—91
Maintain alignment in small sectional dies. Federico Strasser (P.I.) Dec. 8—143
Men of "parts" ... atch machines work at Sylvania. Tangerman & De Groat (report) Sept. 15—113-136
Minimum slug clearance prevents rams. Federico Strasser (P.I.) Mar. 17—133
New processes ... will machine the "unmachinable" (table) Mar. 17—130
Nibbling die slides away from high costs. F. E. Wilson Aug. 18—120
No-strap hinge die. T. H. Hsu (P.I.) Dec. 22—124
Non-Standard threading dies. Neville Palmer (P.I.) Nov. 24—162
Open die forges titanium cones. Bernstein & Nicotera Feb. 18—136
Parts and strips with a die print. (cover) Sept. 15—2
Piece and draw in simple die. T. H. Hsu (P.I.) Sept. 1—144
Piercing die for heavy stock. Federico Strasser (P.I.) Dec. 22—120
Plastic die forms truck cowl for Chrysler Sept. 29—144
Retriever unloads diecaster automatically. R. L. Fromson Dec. 22—100
Rubber-backed dies form rocket-fin curves. T. H. Hsu (P.I.) July 7—161
Scrap ejector for trimming dies. N. Schwartz (P.I.) Sept. 29—134
Sectional dies are easier to finish. P. C. Brashear Mar. 3—161
Sectional dies simplify machining. Fedreico Strasser (P.I.) May 12—179
Shear mechanism on die works every eleventh stroke. Albert Lensky (P.I.) May 26—121
Short-run dies are soldered together. Howard Morgan (P.I.) Feb. 18—168
Simple trick saves toolmaker's time. R. Kreuger (P.I.) Dec. 8—146
Simple zinc-alloy dies speed small orders. J. A. Thomson July 7—138
6-stage progressive die forms heavy stock Aug. 18—112
Small dies ... lots ... costs. Evert Blomgren Feb. 4—108
Standardized die blocks cut tool costs. J. S. Adams Mar. 31—87
Stops for dies. Peter Balsells (Ref. Bk. Sheets) Pts. 1, 2 & 3 Dec. 8—149
Three dies form 1-in. rings. T. H. Hsu (P.I.) Aug. 4—133
3 dies in one press (cover) Dec. 22—2
Timed press tools make and assemble three parts. Rupert LeGrand Feb. 4—93
Trouble shooting die maker. Howard Morgan (P.I.) Dec. 8—144
Two-station broaching die has inverted stripper plate. Anthony Gabriele (P.I.) Feb. 4—134
Upset heading die cuts job time 98%. E. A. De Voss Oct. 13—160
Diesel engines: Packard's precision job-lot tooling makes high-speed diesels for the Navy. B. C. Brashear Nov. 24—149
Dimpling—Hot dimpling forms tough aircraft skin. John Starr Mar. 3—160
Dominion Engineering Works, Ltd. Montreal shop shots June 23—122
Doweling—What's ahead the next ten years in joining and assembly. Mid-Nov. section F—1
Drafting—Construction a tangent to a circle. R. Merry (P.I.) Feb. 18—169
Picture prints speed assembly Aug. 4—128

Dressers:
Look at your diamond wheel dressers. George Daskel Jr. Oct. 27—162
Non-tangent radii on simple dresser. E. C. Jacobs (P.I.) Sept. 15—165
Vise slide traverses wheel dresser. G. H. Dresler (P.I.) Mar. 3—176

Drills and drilling machines:
Arc machining makes hard-to-cut jobs easy. Harding & Matulaitis Mar. 3—136
Avoid broken drill trouble. B. E. Long Jr. Nov. 24—160
Boring tools made from old drills and reamers. G. J. Van Heuke (P.I.) Mar. 17—157
Braced drill cuts at high speed. S. Palmer (P.I.) May 12—176
Centerdrilling setup on turret lathe. J. C. Salinas (P.I.) Mar. 31—119
Centering drill jig grips parts securely. J. G. Decker (P.I.) Aug. 4—129
Centralizing drill jig has high accuracy. W. M. Halliday (P.I.) Feb. 4—132
Depth control for lathe drilling. C. T. Bower Oct. 27—146
Double-duty jig for two drill jobs. C. Y. Lee (P.I.) Mar. 3—180
Double level aligns portable drill. E. A. C. Wright (P.I.) Apr. 28—129
Drill gage always ready. Thomas Trail (P.I.) Sept. 29—133
Drill jig eases square-hole broaching. Chris Sorenson (P.I.) Feb. 18—170
Drill speed and feed charts. J. H. Landvater Pts. 1, 2 & 3 Mar. 17—161
Drilling holes for rough broaching. A. Vetsch (P.I.) May 26—120
Drilling opposed holes without interference. L. Kasper (P.I.) Feb. 4—130
Drilling tiny holes. S. Taylor (P.I.) Oct. 27—145
Drillpress adapter peens rivet heads. Donald Watson (P.I.) Aug. 18—133
Drillpress fixture has chuck on table. Robert Roehler (P.I.) Feb. 18—167
Drillpress jig reproduces holes in dividing-head plate. H. J. Gerber (P.I.) May 26—120
Drillpress safety plug and chuck wrench. Thomas Trail (P.I.) Feb. 18—167
Expanding drill jig takes any bushing size. Tom Brown (P.I.) Mar. 3—176
Functional tooling with unit air-operated drills. A. T. Van Cuterm June 9—124
Gundrills are home grown at Allison. F. G. Senter Sept. 1—110
Hand jig acts fast. C. L. Martin (P.I.) Jan. 7—153
How modern gun-drilling improves hole-making. W. M. Stocker Jr. (report) May 26—109-116
How to drill titanium alloys. Mar. 3—141
How to gun-drill a fixed workpiece. George Cassel Feb. 18—144
How to run a drillpress—report. H. E. Lindsey Feb. 18—147-162
Inverted countersink. A. Vetsch (P.I.) Sept. 1—141
Multiple depth stop for drillpress. Anthony Egle (P.I.) Dec. 22—123
Negative rake helps carbide core drills. W. F. Clark (P.I.) Apr. 28—130

(ed) Editorial (P.I.) Practical Ideas

Offset drill spindle gets under shoulders. U. F. Khoury (P.I.) .. June 9—165
Pneumatic angle drill cuts bearing grooves. S. H. Pearson (P.I.) Mar. 31—120
Portable-drill motor subs for gear motor. Pablo Redl (P.I.) Jan. 7—156
Pulley drive drills hidden hole. C. C. Boston (P.I.) Oct. 13—160
Radial drill turns large rings with remote power. J. P. Ramirez (P.I.) June 9—162
Radial drill working on a large rotor in Italian General Electric plant. (cover) Feb. 18— 2
Remote column lock for radial drill. Irving Epstein (P.I.) Oct. 13—168
Remote light source aids radial drill. Howard Morgan (P.I.) June 23—126
Six tips on drilling small holes in titanium Jan. 21—314
Spotfacer made from old drill. Roger Iletts (P.I.) .. June 9—163
Two-position drill table saves space, tips accuracy. A. V. Jensen Aug. 18—114
Whistle grips extends drill. P. Dawson (P.I.) Apr. 14—176

Drives:
The amplidyne contouring drive. J. L. Dutcher .. Oct. 27—117
Broaching makes an anchor. J. A. Psenka Apr. 14—140
Growing use of adjustable-speed drives prompted new Reliance Electric plant. June 9—179
Racks and pinions drive plastic mold cores. G. H. DeGroat Apr. 28— 97
Shaped driver speeds lathe loading. Anker Olesen (P.I.) Dec. 22—122
Ducts—Bus-duct production goes to town. Lott Steffey .. Sept. 29—105
Fiber ducts save time in wiring machine panels. R. T. Johnstone Dec. 8—105
Dust collectors—Controlling grinding-wheel dust. N. Palmer (P.I.) Nov. 24—161
How Oak Ridge machines beryllium. Case & Watkins Dec. 22— 93
Dynamometers—Change art to science. E. J. Tangerman .. Oct. 13—130

E

Electrical equipment—Be sure your machine tools are electrically safe. June 9—147
Electrical equipment in the metalworking industry. Mid-Nov. section A— 12

Electrodes:
Arc machining makes hard-to-cut jobs easy. Harding & Matulaitis Mar. 3—136
Electrode removes broken parts from deep holes. A. Vetsch (P.I.) Nov. 10—172
Triple electrode spotwelds wire guard. Howard Powell June 9—131
Electrolytic grinding. Metzger & Kecleric Nov. 10—154

Electronics:
Air and ideas make spotwelder automatic. R. P. Roberts Dec. 22—104
Electro-spark machining in Britain. M. G. Seed .. Nov. 10—159
Harness assembly can be a production job. Sperry Gyroscope (cover) Apr. 14— 2
How Sperry harnesses the electron. E. J. Tangerman (report) Apr. 14—143-157
How to balance a machine without an expert with a electronic vibration indicator May 12—173
New processes . . . will machine the "unmachinable" (table) Mar. 17—130
Engineering—Ford unveils new engineering set-up; shows production methods. Jan. 21—294

Engineers:
Centennial of Engineering joins 60 societies. Sept. 15—180
The engineer makes a good foreman. Burnham Finney July 7—123
What to do about engineers. Burnham Finney .. Sept. 15—111

Engines:
British productivity team reports results in engine industry. Sept. 15—179
How Ford extends automaticity to engine handling. M. J. Rowan June 23—113-120
Jet-engine life prolonged with ceramic coating. R. G. Hicks July 21— 99
Jet metalsmiths (apprentices) learn the right way (the hard way) Sept. 15—182
Milling a 30-ton diesel main-frame at Cooper-Bessemer (cover) Dec. 8— 2

Equipment:
Contour grinding requires equipment to suit the job. F. C. Victory .. Sept. 29—106
Letter from the editor—Olympia Exhibition & Hanover Fair. Burnham Finney. Sept. 29—144, Oct. 13—182
Plant-wide planning stretches new-equipment dollars. M. J. Rowan Mar. 17—119
Production Equipment Advisory Committee set up in ODM May 26—174
Spending 50-cent dollars for savings. Burnham Finney May 12—128
Estimating—How to estimate hobbing time. (charts) Johnson & Noling Apr. 14—127
European Tool Show scheduled. Dec. 22—138
Exports—American Machinist Metalworking Facts for 1952. (charts & tables) Jan. 21—129-144

Extrusions:
Hollow extruded forgings conserve critical materials. G. W. Motherwell June 9—119
How Curtiss Wright extrudes propeller blades. Apr. 28—143
Molten glass lubricates extrusions. June 23—141
Recent developments in extrusion. Mid-Nov. section D— 11
Tubes from slugs: 125 extrusions per minute. Frank Charity May 26—100
Why we now make better stainless steels. J. J. Heger (charts & tables) Oct. 13—119

F

Facing—Simple modification speeds angular facing. William Gardiner (P.I.) Nov. 10—173

Feeds:
Don't overlook operator safety in press tool design. L. A. Faulkner (report) Sept. 1—121-136
Drill speed and feed charts. J. M. Landvater Pts. 1, 2 & 3 Mar. 17—161
Feeders and retrievers aid laminated-ring blanking. B. C. Brosheer June 9—128
Four feeds automatize punch press. Matson & King .. Jan. 7—132
Headstock bar feed works on turret lathe. Sherman Mills (P.I.) June 9—163
How to run a drill press—report. H. E. Linsley .. Feb. 18—147-162
Precision lathe feed uses compound angle. Franklin Rieske (P.I.) July 21—179

Files:
Clean your files with a piece of scrap aluminum. K. J. Carson (P.I.) May 26—123
Die-filing jaws hold taper accuracy. Federico Strasser (P.I.) Mar. 3—179
File does emergency knurling. Federico Strasser (P.I.) .. Apr. 28—127

Financial:
Capital expenditures will hit record high in 1952 (charts & tables) .. Feb. 4—146
Capital spending for '53. (chart) Nov. 10—185
$52-billion military budget asked for 1953 Jan. 21—287
Metalworking fights "input-output" economic planning. .. Jan. 21—290

Finishing:
Boring-mill cam follower improves finish, cuts time. W. S. Ball (P.I.) May 12—176
Carbide bur at 90,000 rpm finishes exact Rc61 bores. E. J. Tangerman Mar. 3—142
Discourage corrosion through dry air. G. L. Simpson June 9—127
How Oak Ridge machines beryllium. Case & Watkins .. Dec. 22— 93
How to machine and finish stainless steel. Stevens, Bankoski & Spencer (report) (tables) .. Aug. 4—111-126
How to run a grinding machine. H. E. Linsley (report) Oct. 27—125-140
Plastic—equipment and technique. D. A. Dearle (report) Apr. 28—107-122
Profile gages finished on internal grinder T. J. Roberts (P.I.) Mar. 31—118
Sectional dies are easier to finish. B. C. Brosheer Mar. 3—161
Solid-film lubricant coatings applied by Friden Calculating Machine. Fred Shear .. Sept. 29—178
Superfinishing a mill roll at American Steel & Wire Co. (cover) June 9— 2
What's ahead the next ten years in finishing Mid-Nov. section H— 3
Flame hardening see Heat Treatment.
Flame-heating—How flame and induction heating work. John Ohreski Jan. 7—122
Flanges—Coining controls thickness and location of shell flange May 26—106
Flanging and beading in one operation cuts job time 98%. E. A. De Voss .. Oct. 13—160
Floors—oil absorbent spreader. Fred Lettino (P.I.) Oct. 13—170
Flux—Brazing flux causes spatter. J. M. Dyson (P.I.) .. Apr. 28—126
Ford Motor Co.—How Ford automates production lines. Rupert LeGrand Mar. 17—135-150
How Ford extends automaticity to engine handling. M. J. Rowan June 23—113-120
How Ford plans for low-cost chip handling. M. J. Rowan Apr. 14—134
Latest improvements in press automation at Ford. M. J. Rowan (report) Dec. 8—109-118
Plasticale prototypes speed tooling. Rupert LeGrand (report) May 12—159-164

Forgings:
Aluminum Co. of America expands forging facilities for aircraft components. June 9—177
Cartridge cases are drawn from hot-forged cups. G. H. DeGroat Sept. 15—131
Cold-forge stainless handles in mid-air Nov. 10—126
Developments in forging. Mid-Nov. section D— 6
Dodge automates press forging. Rupert LeGrand .. Sept. 29—123
Hollow extruded forgings conserve critical materials. G. W. Motherwell June 9—119
How Studebaker makes a crankshaft. Foreman & Mishler .. Mar. 3—156
Open die forges titanium cones. Bernstein & Nicotera Feb. 18—136
Pair forging makes giant rotor disks. Sept. 1—138
Pierce, draw hollow steel forgings to 13 tons Aug. 4—146
Foremen—The engineer makes a good foreman. Burnham Finney July 7—123

Forming:
Calculating form tools. J. H. Porsch Mar. 3—145-152
Die quenching precision forms tough alloys at North American Aviation. Corral & Boarts (tables) July 7—125
Hot platen forms magnesium easier. Frank Charity Mar. 17—123
How Ryan hot forms titanium. Jan. 7—125
How to roll back forming costs. A. F. Schuh Mar. 17—132
Men of "parts" watch machines work at Sylvania. Tangerman & DeGroat (report) Sept. 15—113-136
New stretch-forming techniques. Frank Charity Sept. 1—113
Plow mold boards press-formed to shape. Oscar Nelson .. June 9—122
Preformed shapes save time and carbide. Fischer & Pflug Apr. 28—104
6-stage progressive die forms heavy stock. Aug. 18—112
Two operations to form rings. A. Vetsch (P.I.) .. Nov. 10—172
Two operations form full ring. F. M. Butrick Jr. (P.I.) Sept. 29—133
Upset beading die cuts job time 98%. E. A. De Voss .. Oct. 13—160
Foundry see Castings

Furnaces:
Ceramics make furnace fixtures last longer. D. K. Krosch July 21—101
How to maintain heat-treating equipment. T. A. Frischman (report) (tables) Oct. 13—135-146
Toolroom heat treating equipment. (chart) (Ref. Bk. Sheets) Pts. 1, 2 & 3 .. Sept. 15—169

G

Gages and Gaging:
Adjustable roller gage rides with stock. L. F. Karchner (P.I.) May 26—124
Air may solve your gaging problem. W. T. Nystrom Aug. 18—103
Boring-bar hole gage centers automatically. A. Vetsch (P.I.) Apr. 14—179
Combination toolholder gages cut-off lengths. F. C. Lurz (P.I.) May 12—178
Dial-gage arms aid alignment. C. T. Bower (P.I.) May 26—122
Drill gage always ready. Thomas Trail (P.I.) Sept. 29—133
End-mill fixture gages for grinding. L. E. Schryver (P.I.) Apr. 28—127
End-mill gage checks clearance angles. N. Schwartz .. Aug. 4—131
Gaging methods. Mid-Nov. section I— 2
Gaging your hob sharpening and save tools. B. C. Brosheer Aug. 4— 95
Hints for gage design (Ref. Bk. Sheets) Pts. 1, 2 & 3 .. Mar. 3—195
How round is round? A. C. Sanford Nov. 10—124
How to shear to closer limits—good gaging methods. J. J. Murphy May 26—102
Indicating gage floats on future. Allan Clarke (P.I.) June 9—163
Indicator attachment checks extra dimension. R. H. Fry (P.I.) Mar. 17—137
Indicator gage checks machine dovetails. F. H. Lingenfelder (P.I.) Mar. 17—156

(ed) Editorial (P.I.) Practical Ideas

Old micrometer makes height gage. P. Opanowicz (P.I.) Apr. 14—179
Optical comparators simplify inspection of turbine buckets. Aug. 4—104
Profile gages finished on internal grinder. T. J. Roberts (P.I.) Mar. 17—158
The right gage at the right time. S. R. Gable Jan. 7—144
Scissors gage measures hidden diameters. L. A. Pitteils (P.I.) Oct. 13—171
Shim gage checks taper. R. Merry (P.I.) Mar. 12—177
Slot checking gage has dial indicator. R. W. Sterrat (P.I.) Feb. 4—133
Special gage blocks get into bores. Charles Borrows (P.I.) June 23—125
Step in gage fixture aligns locating plug. F. A. Adams (P.I.) June 9—163
Tolerances for plug and ring gages. (Ref. Bk. Sheets) Feb. 18—177
Toolbits scribe for height gage. K. J. Carson (P.I.) Sept. 1—142
Vernier action improves height gage. Peter Opanowicz (P.I.) Apr. 28—126
Vise gage locates part for clean-up. N. Palmer (P.I.) Aug. 4—134

Gears and Gearing:
300 powder-metal gears an hour. (cover) Sept. 1— 2
Gear-centering device locates shafts for boring. J. McDonald (P.I.) May 26—123
Gear making Mid-Nov. section E—24
Good tools, plus experience make better gears. Del Hansen Feb. 18—140
Gravity bearings support idler gear. R. Merry (P.I.) July 21—127
How to cut gears without a dividing head. B. A. Rogers (P.I.) Apr. 28—126
How to design and apply master gears. Fred Bohle (charts & tables) Dec. 8—125
Induction-hardened gears show little distortion. L. G. Miller July 21—141
Ingenious tools make complex metal powder parts. G. H. DeGroat Sept. 1—103
Measurement of case depth. James Sorenson (table) (Ref. Bk. Sheets) Mar. 31—129
New gear standards approved at annual meeting of American Gear Mfrs. Assn. June 23—140
Pin measurement of face gears. Silvaet & Francis (Ref. Bk. Sheets) Pts. 1, 2 & 3 May 12—183
Pin measurement tables for involute gears. R. E. Rawling (Ref. Bk. Sheets) Pts. 1 & 2 June 23—133, Pts. 3, 4 & 5 July 7—165, Pts. 6, 7 & 8 July 21—133, Pts. 9 & 10 Aug. 4—137
Simple mechanism increases gear-shaper capacity. O. F. Lambert (P.I.) Sept. 1—140
Teething a turret ring gear at Detroit Tank Arsenal (cover) Mar. 3— 2
Germany—The rising German challenge. B. Finney (charts & tables) May 26—85-98
Tool builder, grabbed by Russians, sets up shop in West July 21—147
Glass—How to apply metal to glass and ceramics. Samuel Wein July 7—147-154
Molten glass lubricates extrusions. June 23—141

Grinders and Grinding Machines:
Abrasive belts grind carbide. G. H. DeGroat Dec. 8—102
Attachment feeds grinder on lathe. F. C. Lurz (P.I.) Mar. 17—156
Belt grinding tapers wing skins. J. R. Botns Sept. 1—134
Carbide toolbit reground only on top. J. M. Askin (P.I.) Mar. 17—153
Cbr ools carbide grinders. A. B. Albrecht (table) Dec. 8— 97
Compound angles simplified. R. G. Vare (P.I.) Feb. 4—133
Controlling grinding-wheel dust. N. Palmer (P.I.) Nov. 24—161
Cost of grinding carbide. H. W. Wagner (Ref. Bk. Sheets) (tables) Apr. 14—183
Cutter-grinder arbor adjusts for grinds. H. R. Gillham (P.I.) June 23—126
Diamond bort—why and how we must conserve it; alternate methods for grinding. Anderson Ashburn Nov. 10—151
Disk grinder conveyor mass-finishes raw castings. J. F. Rudnick (P.I.) July 21—126
Eccentric grinding equipment forms sewing machine shafts. F. C. Lurz (P.I.) Feb. 4—131
Eight ways to grind machine-tool ways. R. R. Baldenhofer Mar. 31— 88
Electrolytic grinding. Metzger & Keelerie Nov. 10—154
Electrolytic grinding cuts carbides. Oct. 13—189
Emergency surface grinder. Gerald Alic (P.I.) Sept. 29—133
End-mill fixture gages for grinding. L. E. Schryver (P.I.) Apr. 28—127
Grinder safety brake. Haim Murro (P.I.) Sept. 15—164
Grinding centers for hardened parts. Neville Palmer (P.I.) Dec. 8—145
Grinding fixture aids die manufacture. Rupert LeGrand Nov. 24—134
Grinding, lapping, honing Mid-Nov. section E— 15
Grinding shaving tools on an optical grinder. N. Palmer (P.I.) Nov. 24—160
Grinding thin stock. R. J. Dodson (P.I.) Aug. 18—122
Grinding wheel code is permanent identification. H. J. Gerber (P.I.) Aug. 18—132
Grinding wheel on lathe trims up chuck jaws. I. J. Peacock (P.I.) Mar. 3—178
Guide for dressing. G. F. Burnley (P.I.) Sept. 1—142
HSS form tools salvaged by regrinding. A. E. Salmons (P.I.) July 21—130
Hand-controlled shaper grinds cutters. Max Kaufunkel (P.I.) May 12—179
Hand grinder attaches to surface grinder. W. T. Whitman (P.I.) Aug. 18—133
Hinged work holders save grinder centers. Tom Brown (P.I.) Apr. 14—176
How to conserve diamond wheels. E. T. Larson (Ref. Bk. Sheets) Pts. 1 & 2 Feb. 18—173
How to grind boring tools. E. J. Kaiser (Ref. Bk. Sheets) Pts. 1 & 2 Mar. 31—125
How to grind titanium. Dr. L. P. Tarasov (charts & tables) (report) Nov. 10—135-146
How to run a grinding machine. H. F. Linsley (report) Oct. 27—125-140
How and why taps are precision ground. S. W. Lovejoy June 9—135-142
Internal grinding a large bore. B. L. Adamson (P.I.) Nov. 24—162
International Harvester grinds a tractor crankshaft. (cover) Sept. 29— 2
Look at your diamond wheel dressers. George Daskel Jr. Oct. 27—142
Miller grinds tools. Eduard Gast (P.I.) Apr. 28—127
New processes . . . will machine the "unmachinable" (table) Mar. 17—130
Pedal operates grinder-tailstock lever. Tom Brown (P.I.) Feb. 18—169
Plastic threads cut by grinding. J. O. Wyld (P.I.) Mar. 3—178
Precision contour grinding makes better tools. F. C. Victory Pt. 1 Sept. 15—154, Pt. 2 Sept. 29—106
Preformed shapes save time and carbide. Fischer & Pfing Apr. 28—104
Profile gages finished on internal grinder. T. J. Roberts (P.I.) Mar. 31—118
Setup block control threading-tool angle. L. H. Coombs (P.I.) July 7—158
Sharpen pencils with old grinding wheels. John Beck (P.I.) Sept. 15—163
Simple angle-dresser. G. F. Burnley (P.I.) Sept. 1—141
Simple sine bar sets grinding angles. R. G. Vare (P.I.) July 7—162
Surface grinder from bench drillpress. L. T. Smith (P.I.) Oct. 13—168
Thin grinding wheel forms chip breakers. Robert Faulkner (P.I.) June 23—127
Titanium ground by Lockheed. Mar. 3—175
Tool sharpener does odd shop jobs. R. K. Wimburn (P.I.) June 9—165
Wet belt grinding speeds production of extruded cylindrical stock. Olton & Dyer Dec. 8—106

Grooves—Grooving cutter uses carbide—toolbits. Stanley Kusmer (P.I.) Dec. 8—146
Pneumatic angle drill cuts bearing grooves. S. H. Pearson (P.I.) Mar. 31—120

Guns see Munitions

H

Hammers:
Hammer isolation—revised method Aug. 18—118
How to hit hard blows softly. J. E. Hyler Feb. 4—128
Handicapped—Employing physically handicapped workers pays off. W. H. Kelly Dec. 22—102
Sightless employees pull their weight. F. M. Friman Feb. 4—102
Handles—Shock-absorbing flatter handle. D. G. Peterson (P.I.) Dec. 22—123
Hanover Fair, Germany—Letter from the editor. Burnham Finney Sept. 29—144, Oct. 13—182

Heat Treatment:
Ceramics shield stainless for jets. R. G. Hicks July 21— 99
Flame hardening mechanite castings. Dr. C. R. Austin (tables) May 12—165
Hot dimpling forms tough aircraft skin. John Sturt Mar. 3—160
Hot molding increases scope of powder metallurgy. J. F. Kuzmick July 7—132
Hot plates forms magnesium easier. Frank Charity Mar. 17—123
How flame and induction heating work. John Obreski Jan. 7—122
How to cool oil-quench tanks. C. L. Ringquist Aug. 18—106
How to maintain heat-treating equipment. F. A. Frischman (report) (tables) Oct. 13—135-146
How to understand brass. Samuel Stockheim Oct. 13—151
How to work with beryllium-copper strip. J. T. Richards (charts & tables) Mar. 31—99-114
Inconel brazed in hydrogen. (cover) July 21— 2
Ingenious tooling solves tough milling problems. E. Disco Sept. 29— 98
Spray and sinter to make high temperature alloy parts. Cline, Thurston & Wulff Mar. 3—172
Sub-zero hand-tool failures suggest new steels and treatments. Sam Tour (tables) Nov. 24—154
Tanks roll on welded wheels. Lawrence Maas June 23—106
This furnace processes these parts Apr. 14—139
Toolroom heat-treating equipment (chart) (Ref. Bk. Sheets) Pts. 1, 2 & 3 Sept. 15—169
Tubes from slugs: 125 extrusions per minute. Frank Charity May 26—100
What's ahead the next ten years in heat-treating Mid-Nov. section G— 1
Why we now make better stainless steels. J. T. Heger (charts & tables) Oct. 13—119

Hinges—No-scrap hinge die. T. H. Hsu (P.I.) Dec. 22—124

Hobs and Hobbing:
Gage your hob sharpening and save tools. R. C. Brosheer Aug. 4— 95
How to estimate hobbing time. Johnson & Nolting (charts) Apr. 14—127
Interchangeable mandrels to cut hobbing costs. Del Hansen May 12—138
We buy tools from past performance. J. M. Finally Apr. 14—174

Hoists—Quick-sling lifts vertical tanks. Pablo Redl (P.I.) Sept. 29—133
Safety signal for hoist control. Thomas Trail (P.I.) Nov. 10—174

Holes:
Drilling tiny holes. S. Taylor (P.I.) Oct. 27—145
Half-spheres measure hole center-distance. Haim Murro (P.I.) Sept. 29—131
How modern gun-drilling improves hole making. W. M. Stocker Jr. (report) May 26—109-116
How to control coordinate tolerances. A. L. Levitt Oct. 13—166
Microhoraching . . . new technique for tiny, odd shaped holes. J. S. Denison Mar. 3—134
Trepanning speeds production of deep holes. F. W. Lucht Mar. 31— 96

Honers and honing—Grinding, lapping, honing Mid-Nov. section E15
Spider honing cutter finishes diesel sleeves. J. P. Ramirez (P.I.) Jan. 7—155

Hydraulic equipment—Giant size, plus accuracy makes turbine building tough. G. H. DeGroat Nov. 10—168
Hydraulics and pneumatics for machine tools Mid-Nov. section A19
Hydraulic Press Mfg.—Marks 75th year with record output July 21—144

I

Imports—Big jump in 1952 imports of foreign machine tools Feb. 18—182

Indexing:
American Machinist metalworking price index announced Mar. 31—132
American Machinist wholesale prices indexes for machinery Mar. 3—202
Circular index table. John Stewart (P.I.) Oct. 27—147
Reamer alignment counteracts table-indexing errors. W. S. Jaro (P.I.) Feb. 18—166
Simple, rugged index plate does universal holding jobs. N. Palmer (P.I.) Aug. 18—134
Wide index plate finger compensates for cutter width. Robert Roedder (P.I.) July 7—159

Indicators:
Adjustable holder for "last word" indicator. H. H. Opanowicz (P.I.) Dec. 8—143
Beam compass supports indicator. Leopold Freimark (P.I.) June 23—125
Dial indicator checks steadyrest setups. Tom Brown (P.I.) Apr. 14—180
Indicator attachment checks extra dimension. R. H. Fry (P.I.) Mar. 17—157
Taper indicators added to tailstock. O. C. Brage (P.I.) Apr. 14—177

Induction Heating:
How flame and induction heating work. John Obreski Jan. 7—122
Induction brazes squirrel cage. Brace & Fitzgerald Mar. 17—124

(ed) Editorial (P.I.) Practical Ideas

Induction brazes squirrel cage at West inghouse (cover) . . . Mar. 17— 2
Induction brazing can be used for copper and copper-alloy parts. E. M. Laughner . . . Nov. 24—138
Induction hardened gears show little distortion. L. G. Miller . . . July 21—141
Special setups speeds production of 20-mm AP shot. F. M. Beede . . . July 21—112
Industrial Packaging and Materials Handling Exposition 7th annual show . Oct. 27—158

Inspection:
"Cumulative sampling" boosts shop output 22%. C. H. Latter . . . Sept. 29— 95
Inspection gantry provides high reference surface. R. H. Fry (P.I.) July 7—158
Maybe you have toolcrib trouble, too! Robert Galloway . . . June 9—152
Optical comparators simplify inspection of turbine buckets . . . Aug. 4—104
Plastics make inspection crystal clear . . . July 21—140
Sonic tester checks bonding of honeycomb panels. H. O. Williams Sept. 1—116
What's ahead the next ten years in inspection and testing Mid-Nov. section I— 1
Insulation—Noise . . . a shop problem (report) . . . Dec. 22—109-116
Insurance—Are you paying too much for insurance? W. W. McCall . . . June 23—104
Sorry you're not covered—fire insurance. W. W. McCall . . . Nov. 24—158
Inventions—1877 to 1952 . . . a highlight survey of development . . . Mid-Nov. *3
Inventory—How to cut inventory costs. D. E. McNeil (charts & tables) . . . Sept. 29—111-122
Iron—New data on ductile cast iron Apr. 28—106
What constituents affect machinability of gray irons? Loria, Boulger & Shaw (charts) . . . Oct. 27—122
Isometric drawing—Picture prints speed assembly . . . Aug. 4—128

J

Japan—Seeks new markets for overaccelerated economic capacity . . . Dec. 8—160

Jet Propulsion Engines:
Boeing Airplane equipment to taper-mill wing skins for B-47 stratojets. Jerry Sanford . . . Apr. 14—166
GE cuts cost of making jet blades . . . Mar. 3—201
Special duplicators speed experimental jet-engine blades M. J. Rowan Mar. 3—166

Jigs and Fixtures:
Advances in jigs and fixtures . . . Mid-Nov. section C6
Air-cushion for heavy jigs. C. T. Bower (P.I.) . . . Nov. 24—162
Air and ideas make spotwelder automatic. R. Dec. Roberts . . . Dec. 22—104
Ball-bearing fixture bends plates. G. C. Best (P.I.) . . . Mar. 31—118
Cable clamping jig. Irving Epstein (P.I.) . . . Oct. 27—145
Cam for jig clamping. R. Mery (P.I.) . . . Dec. 8—145
Centralizing drill jig has high accuracy. W. M. Halliday . . . Feb. 4 *132
Double-duty jig for two drill jobs. C. Y. Lee (P.I.) . . . Mar. 3—180
Drill jig eases square-hole broaching. Chris Sorenson (P.I.) . . . Feb. 18—170
Drillpress fixture has chuck on table. Robert Roedder (P.I.) . . . Feb. 18—167
Drillpress jig reproduces holes in dividing head plate. H. J. Gerber (P.I.) . . . May 26—120
Eccentric turning attchment. W. Lewis (P.I.) . . . Sept. 29—130
Expanding drill jig takes any bushing size. Tom Brown (P.I.) . . . Mar. 3—176
Expanding fixture grips round collars. N. F. Khoury (P.I.) . . . July 7—158
Fulcrum fixture on mill cuts large radius. A. T. Renson (P.I.) June 23—127
Functional tooling with unit air-operated drills. A. T. Van Cutsem . . . June 9—124
Guide for dressing. G. F. Burnley (P.I.) . . . Sept. 1—143
Hand jig acts fast. C. L. Martin (P.I.) . . . Jan. 7—153
Holding blocks do a tough fixturing job. S. K. Rexford . . . Jan. 7—150
How to design diamond pin locators. E. J. LaBroad (chart) . . . Dec. 8—108
Ingenious machines weld thin-wall stainless tanks. R. L. Brown . . . Nov. 24—125
Inverted countersink. A. Vetsch (P.I.) . . . Sept. 1—141
Jig bores two holes at once. Halmar Dahl (P.I.) . . . Dec. 8—142
Master fixtures master assembly troubles. Frank Charity . . . Mar. 31— 92
Planer fixture bends bolts. Stanley Hodge (P.I.) . . . Mar. 31—120
Punching out flash on drillpress at Yoder Die Casting . . . Aug. 18—130
Screw jig simplifies cutoff. F. M. Butrick Jr. (P.I.) . . . May 26—120
Screw-clamped fixture has fast action. Tom Brown (P.I.) . . . Mar. 17—154
Shell-chucking fixture speeds turning operations. D. G. Nolle (P.I.) . . . Apr. 28—125
Simple fixture turns many radii. Donald Watson (P.I.) . . . Dec. 22—121
Slotting fixtures load rapidly. B. P. Fortin Sr. . . . Apr. 28—102
Specially designed fixture bends high-strength extruded shapes. F. C. Hoffman (report) . . . July 21—115-122
Strip-cooling fixture makes heat exchangers. Bario Baltsch (P.I.) . . . July 7—159
Tube-connected elbows level large fixtures. R. G. Vate (P.I.) . . . Mar. 31—121
Jugoslavia—What about Tito? E. P. Warner . . . July 7—178

K

Knurling:
Chrome plate wear resistance upped by knurling. E. F. Discoe . . . Aug. 4—101
File does emergency knurling. Federico Strasser (P.I.) . . . Apr. 28—127
Knurling (Ref. Bk. Sheets) Pts 1, 2 & 3 (tables) . . . Dec. 22—127

L

Labor:
After the strike—how does it go? . . . Aug. 17—151
Apprentices get new draft protection . . . Aug. 18—153
Bonus for not working for maintenance crew. Pablo Redl (P.I.) Sept. 29—131
CIO family plan—United power Sept. 1—159
Cleveland personnel survey checks fringe treads . . . Nov. 10—189
Employing physically handicapped workers pays off. W. H. Kelly . . . Dec. 22—102
Employment up in metalworking . . . Mar. 17—169
Fringe benefits cost 30c per hour study of Cleveland Industries show July 21—142
Handicapped employees pull their weight E. M. Feiman . . . Feb. 4—102
How to welcome new employees. J. B. Bennet (Ref. Bk. Sheets) Pts 1 & 2 . . . Oct. 27—151
How will you pick your assistant? A. M. Cooper . . . Aug. 18—116
Labor is the big factor in friction-sawing costs . . . Sept. 15—153
Labsonite Machine Tool using Scanlon Plan cited as high standard in industrial labor peace . . . Dec. 22—139
Make research data useful to the shop man. Dr. M. Kronenberg (tables) . . . Sept. 15—145
NLRB decision may lead to union influence on subcontractors . . . Dec. 8—163
New labor leaders spark new vitality; merger doubtful . . . Dec. 22—136
Noise . . . a shop problem (report) . . . Dec. 22—109-116
Off the job accidents cost $3 billion a year. A. S. Johnson . . . Oct. 13—148
Outlook bright for labor peace in metalworking industries . . . July 21—145
Pentagon "watch dog" office helps to stop strikes in defense plants Jan. 7—167
Plan act to place more defense work in Detroit, other labor-surplus areas . . . Feb. 18—181
Shop pensioners disprove the rules (report) . . . Apr. 14—162-164
Something for the boys. Burnham Finney . . . Apr. 28— 89
The strangers in your plant. Burnham Finney . . . Feb. 18—129
Tyranny is the word for it. Burnham Finney . . . June 9—117
Laminations—Feeders and retrievers aid lamination blanking. B. C. Brosheer . . . June 9—128
Lapping and lapping machines—Grinding, lapping, honing . . . mid-Nov. section E15
Small D6 motor runs lapping setup. G. T. Miller (P.I.) . . . Aug. 18—131

Lathes:
Accurate sphere turner driven by lead-screw. A. F. Kirk (P.I.) . . . Feb. 18—168
Alignment pins locate tailstock for taper. F. M. Butrick Jr. (P.I.) . . . June 9—161
Antifriction steadyrest jaws. Dale Orr (P.I.) . . . Sept. 1—143
Attachment feeds grinder on lathe. F. C. Lurz (P.I.) . . . Mar. 17—156
Ball-bearing tube center. H. Woerle (P.I.) . . . Oct. 27—145
Cam lock in mandrel prevents slip. Del Hansen . . . July 7—137
Centerdrilling setup on turret lathe. J. C. Salinas (P.I.) . . . Mar. 31—119
Contour turning lathes great grandpa used still in use. **Reed & Tweddle** . . . Nov. 10—119
Converted lathe bores ball sockets. C. D. Mackinnon (P.I.) . . . Aug. 18—131
Depth control for lathe drilling. C. T. Bower (P.I.) . . . Oct. 27—146
Double-end turret holds many extra tools. F. H. Colvin (P.I.) . . . Apr. 28—127
Double tool saves steel. Robert Laimborck (P.I.) . . . May 12—178
Eight ways to grind machine-tool ways. R. R. Baldenhofer . . . Mar. 31— 88
Headstock bar feed works on turret lathe. Sherman Mills (P.I.) June 9—163
High-speed setup cuts interrupted helixes. John Stewart (P.I.) . . . May 26—124
Homemade floating diehead. C. Y. Lee (P.I.) . . . Sept. 15—163
How to run an engine lathe. H. E. Linaley (report) . . . May 12—143-158
How to set up a heavy angleplate. Thomas Gray (P.I.) . . . Oct. 13—169
Lathe doubles as boring mill. Lewis Cranston . . . Nov. 24—156
Lathe and powered faceplate make versatile T lathe. C. F. Welch (P.I.) . . . Feb. 18—166
Lathe saddle works like turret. S. Taylor (P.I.) . . . July 21—130
Micrometer toolblock shift saves lathe tools. F. M. Butrick Jr. (P.I.) June 9—166
Monarch Machine, Sidney, Ontario revamps production line, adds new plant for T lathes . . . Nov. 10—187
Power feed shots shafts in lathe setup. Tom Brown (P.I.) . . . June 23—128
Precision lathe feed uses compound angle. Franklin Rieske (P.I.) . . . July 21—129
Saddle-feeding lever speeds bench lathe. I. J. Peacock (P.I.) . . . Aug. 4—132
Scroll-cutting lathe rig. Allan Clarke (P.I.) . . . Jan. 7—153
Seagoing lathe weathers all blows . . . Mar. 31—116
Shaped driver speeds lathe loading. Anker Olesen (P.I.) . . . Dec. 22—122
Shop-built bench lathe takes large range of work. R. H. Fry (P.I.) . . . June 23—124
Simple connection powers tailstock. J. Woerle (P.I.) . . . Mar. 31—118
Spindle adapter for lathe centers small-size bars. Paul Jeanvet (P.I.) June 9—162
Spring headstock center increases shoulder ing accuracy. I. J. Peacock (P.I.) . . . May 26—123
Spring-winder attachment powered by lathe spindle. C. Y. Lee (P.I.) Jan. 7—156
Strengthened engine lathe does tough spanning jobs (P.I.) . . . Aug. 4—129
Tailstock attachment . . . braces slender work. C. Y. Lee (P.I.) . . . Feb. 4—133
Tailstock handwheel locks quickly. I. J. Peacock (P.I.) . . . May 26—121
Taper indicator added to tailstock. O. C. Brage (P.I.) . . . Apr. 14—177
Taper-turning tool tailstock guided. C. T. Bower (P.I.) . . . Aug. 18—132
Toolroom conversion produces semi-turret lathe . . . Aug. 4—107
Traversing friction meter checks carriage motion. Fristedt & Multberg (P.I.) . . . June 9—162
Tube-turning tool tailstock mounted. Floyd Geltz (P.I.) . . . Sept. 15—162
Turning and boring developments . . . Mid-Nov. section E7
Turning a jet compressor frame (cover) . . . Nov. 10— 2
Turning a parabola. James Heatley (P.I.) . . . Oct. 13—169
Turret lathes build turbojets . . . Feb. 4—119
Turret mirrors save steps in deep-hole boring. Hadley Jacobs (P.I.) . . . May 12—176
Turret slide and miller cut cams. Allan Clarke (P.I.) . . . Mar. 17—154
Welded lathe tools make flycutters. Allan Clarke (P.I.) . . . Mar. 17—156
Wood stock tubes cut shop waste. N. Palmer (P.I.) . . . Aug. 4—130

Layout:
Bending-line layout. W. M. Stocker, Jr. (chart) . . . July 21—111
Calculating form tools. J. H. Porsch . . . Mar. 3—145-152
Compound angles simplified. R. G. Vare (P.I.) . . . Feb. 4 *133
Construction of a tangent to a circle. R. Mery (P.I.) . . . Feb. 18—169
How Sperry harnesses the electron. E. J. Tangerman (report) . . . Apr. 14—143-157
Scribing small shafts. C. G. Nelson (P.I.) . . . Jan. 7 *153
Leipzig Fair—Iron curtain lifts to reveal Russian machine tools . . . Dec. 8—131

Lights and Lighting:
Flashlight on rule gets behind machinery Fred Lettino (P.I.) . . . July 21—128
Remote light source aids radial drill. Howard Morgan (P.I.) . . . June 23—126

(ed) Editorial (P.I.) Practical Ideas

Signal light monitors air mechanisms. W. T. LaLond (P.I.) Feb. 4—132

Loaders:

Feeders and retrievers aid lamination blanking. B. C. Brosheer June 9—128
Hinged work loaders save grinder centers. Tom Brown (P.I.) Apr. 14—176
Slotting fixtures load rapidly. R. P. Fortin Sr. Apr. 28—192

Lubrication:

Automatic center lubricator. C. T. Bower (P.I.) Aug. 18—133
Development of lubrication in metal working Mid-Nov. section A20
Grease-gun pump. J. C. Salinas (P.I.) Mar. 31—120
How to use molybdenum disulphide as a lubricant. E. M. Davison (charts) Dec. 22—106
Molten glass lubricates extrusions. June 23—141
Oil pan controls fluid quantity. Fred Lettow (P.I.) Sept. 1—140
Pierce-and-draw forging method uses a graphite-grease lubricant Aug. 4—146
Solid-film lubricant dustings applied by Friden Calculating Machine. Fred Shear Sept. 29—128
Soluble oil lubricates punches. Federico Strasser (P.I.) May 12—178
Sprayed vapor ups tap life and speed. W. M. Stucker Jr. Jan. 7—121

M

Machinery:

An American abroad looks at British machine tools Nov. 24—176
American Machinist Metalworking Facts for 1952 (charts & tables) Jan. 21—129-144
American Machinist 1952 Production Preview Jan. 21—145-272
Big jump in 1952 imports of foreign machine tools Feb. 18—182
Capital expenditures will hit record high in 1952 (charts & tables) Feb. 4—146
Distributors stress problem of keeping machine-tool industry strong Apr. 28—142
Few U. S. machine-tool orders disappoints Japanese builders Apr. 28—141
Germans enjoy machine-tool boom, spurred by western rearmament Apr. 14—194
German machines dominate Canadian fair June 23—139
Idle machine tools put to work under National Production Authority inventory program July 7—182
Increase machine capacity with control charts. Joseph Manuele (charts) Feb. 18—131
Iron curtain lifts to reveal Russian machine tools Dec. 8—171
National Machine Tool Builders Assn. studies domestic and foreign problems May 12—193
National Production Authority amends M-41 to allow shipment of unrated machine-tool orders Aug. 4—130
New processes . . . will machine the "unmachinable" (table) Mar. 17—120
Officials blamed for tool shortage Feb. 4—148
Permanent machine-tool reserve plan held essential to security Apr. 14—191
Preference list prepared for tooling Mar. 17—171
Progressive decontrol of machine-tool industry advocated at National Machine Tool Builders' Assn. fall meeting Nov. 24—174
Rebuilding a boring machine pays off. Paul Jordan Jan. 7—*142
The rising German challenge. B. Finney (charts & tables) Dec. 8—98
Sales at record level June 9—128
Soviets set new 5-year plan goals Sept. 1—156
Time for a new look. Burnham Finney Dec. 22—91
$788 million of machine-tool purchases spurred by Economic Cooperation Admin. & Mutual Security Admin. Dec. 22—107
U. S. buying abroad for NATO swings into high gear Aug. 4—143
Used machinery dealers told of need for central control of tool reserve May 26—135
West Coast survey shows machine lack Sept. 15—181
What's ahead the next ten years in machining Mid-Nov. section E
What's ahead the next ten years in rebuilt equipment Mid-Nov. section M
When and why a special machine? C. P. Farr Mar. 17—126
Write-offs should be optional. Burnham Finney Apr. 14—123

Magnesium:

Development of magnesium Mid-Nov. section A7
Hot platen forms magnesium easier. Frank Charity Mar. 17—123
Safe handling of magnesium Pts 1 & 2 (Ref. Bk. Sheets) Sept. 1—147
Magnesium Assn. meeting discusses plane wings Nov. 24—178

Magnetic Equipment:

Cosmotron "doughnut" magnet is 288 shop-made sandwiches Nov. 10—138
Low-voltage magnetic holding. Axel Andetzer May 12—127
Magnetic holding for face milling (cover) May 12—2
Magnets find balance on flywheels. A. H. Poole (P.I.) July 21—127

Maintenance:

Bonus for not working paid maintenance crew. Pablo Redl (P.I.) Sept. 29—131
$5 billion will be spent for plant maintenance Jan. 21—292
How to maintain heat-treating equipment. T. A. Freshman (report) (tables) Oct. 13—135-146
Repair of iron castings (Ref. Bk. Sheets) Pts 1, 2 & 3 Sept. 29—137
Pts. 4 & 5 Oct. 13—175
What's ahead the next ten years in plant services Mid-Nov. section J

Management:

Are you paying too much for insurance? W. W. McCall June 23—104
How to welcome new employees. J. B. Benner (Ref. Bk. Sheets) Pts 1 & 2 Oct. 27—151
How will you pick your assistant? A. M. Cooper Aug. 18—116

Mandrels:

Ball grippers retain work on tapered turning mandrel. Craig Kerr (P.I.) July 7—160
Cam lock in mandrel prevents slip July 7—137
Expanding mandrel works with chuck. M/Sgt. J. K. Wood (P.I.) Aug. 4—134
Interchangeable mandrels to cut hobbing costs. Del Hansen May 12—138
Mandrel on sliding-jaw chuck grips work on the ID. Allan Clarke (P.I.) Feb. 4—134
Manufacturers Industrial Supply Corporations. New tool-supply organizations Dec. 22—138
Markers and marking. Off-center pins mark centerlistances. P. E. Myers (P.I.) June 23—134
Martin, Glenn L. Co. shop shots Aug. 4—102

Materials:

Appliance makers probe ways to cut use of critical materials Feb. 18—180
Decontrol near for materials, wages and prices May 12—190
Materials Policy Commission reports serious materials shortages seen in 25 years July 7—176
Public airing for the Paley Report Dec. 8—162
What's ahead the next ten years in materials and components Mid-Nov. section A2

Materials Handling:

Alco tooling assembles the M-47 hybrid. E. J. Tangerman (report) Aug. 18—119-126
An arm with mechanical muscle Nov. 24—129
Automatics roll off the line. E. J. Tangerman Sept. 15—137
Automation triples pail-line output. E. F. Paquette Dec. 22—98
Before you improve materials handling ask yourself is this trip necessary? C. W. Metter June 9—143
Better handling saves building space. J. E. Wiltrakis Dec. 8—136
Boeing Airplane rebuilds overhead monorail system Dec. 8—160
Cold-forge stainless handles in mid-air Nov. 10—126
Conveyors and convenience cut switch-assembly costs at McGill Mfg. Co. Carlson May 12—136
Developments in materials handling Mid-Nov. section J9
Feeders and retrievers aid lamination blanking. B. C. Brosheer June 9—128
Full conversorization eliminates manual chip handling. D. C. Peterson Oct. 13—162
How aluminum bonding is keyed to production. W. M. Stucker Jr. July 21—108
How Ford extends automaticity to engine handling. M. J. Rowan June 23—113-120
How Ford plans for low-cost chip handling. M. J. Rowan Apr. 14—134
Latest improvements in press automation at Ford. M. J. Rowan (report) Dec. 8—109-158
Men of "parts" watch machines work at Sylvania. Tangerman & DeGroat (report) Sept. 15—133-136
Safe handling of magnesium (Ref. Bk. Sheets) Pts 1 & 2 Sept. 1—147
"Shop in stockroom" provides point-of-use storage. M. J. Rowan Feb. 4—124
Stacked conveyors boost pressline flexibility. George Corse June 9—132
Transfer cars keep assembly moving. E. L. Brainard Nov. 10—132
Tricky tooling turns out tubes at Sylvania Electric Products Inc. Tangerman & DeGroat June 23—97

Measuring:

Anvil bush centers measuring rods. A. Vetsch (P.I.) June 23—125
Pin measurement of face gears. Silvagni & Francis (Ref. Bk. Sheets) Pts 1, 2 & 3 May 12—183
Metallurgical control Mid-Nov. section I7

Metals:

Bigger allocations of steel, copper, aluminum to benefit small users Apr. 14—190
Ceramics shield stainless for jets. R. G. Hicks July 21—99
"Hot copper sandwich" may boost jet performance June 9—157
How to apply metal to glass and ceramics. Samuel Wein July 7—147-154
Metal Show in Print Oct. 13—192
Metals in brief Mid-Nov. section A9
No let up in controls over use of metals in civilian products (charts) Jan. 21—288
Pick the right metal for flame hardening mechanite castings. Dr. C. R. Austin (tables) May 12—168
Preferred thicknesses of sheet metals (Ref. Bk. Sheets) (tables) Oct. 27—155
Sandwich structures are simple May 26—118

Metalworking:

American Machinist Metalworking Facts for 1952 (charts & tables) Jan. 21—129-144
American Machinist 1952 Production Preview Jan. 21—145-272
Amertool travel group of 33 Japanese complete visits to U. S. metalworking shops Dec. 22—137
Canada goes full blast on defense, lets civilian metalworking slide Nov. 10—188
Capital expenditures will hit record high in 1952 (charts & tables) Feb. 4—146
Doing the impossible. Burnham Finney Mar. 3—127
1877 to 1952 . . . a highlight survey of development Mid-Nov. *3
Electro-spark machining in Britain. M. G. Seed Nov. 10—159
How high vacuum aids metalworking. Frank Charity July 21—102
In this union there is strength (cover) July 7— 2
Men of "parts" watch machines work at Sylvania. Tangerman & DeGroat (report) Sept. 15—113-136
Metalworking industries fight "input-output" economic planning Jan. 21—290
Outlook bright for labor peace in metalworking industries July 21—145
Seventy-five years of metalworking production (chart) Mid-Nov. 33
Soviets set new 5-year plan goals Sept. 1—156
What's ahead the next ten years Mid-Nov. *20-33
A ten year look ahead . . . here's what can happen (chart) May 26—136
What's ahead the next 10 years in metalworking production Mid-Nov. section A
Meters—Traversing friction meter checks carriage motion. Fristedt & Multberg (P.I.) June 9—162

Micrometers:

Anvil bush centers measuring rods. A. Vetsch (P.I.) June 23—125
Bench micrometer checks slots and holes. Sam Winston (P.I.) June 23—126
Micrometer toolblock shift saves lathe tools. F. M. Butrick Jr. (P.I.) June 9—166
Old micrometer makes height gage. P. Opanowicz (P.I.) Apr. 14—179
Shimstock is cheaper than micrometers. C. D. Carlsen (P.I.) Dec. 22—121

Milling and Milling Machines:

DeLaval Steam Turbine Co. gang-milling pump castings (cover) Apr. 28— 2
Developments in milling Mid-Nov. section E12
Dual-purpose boring mill (cover) Oct. 27— 2
End-mill gage checks clearance angles. N. Schwartz (P.I.) Aug. 4—131
Fulcrum fixture on mill cuts large radius. A. T. Benson (P.I.) June 23—127
Geared shafts milled in pairs. R. G. Vare (P.I.) July 7—161
High rake angles aid milling performance. Crawford & Merchant July 7—172
High speed milling (cover) Aug. 4 *2
How to mill a large radius. E. Winkler (P.I.) Oct. 13—170

(ed) Editorial (P.I.) Practical Ideas

How wing skins for B-47 stratojets are taper-milled. Jerry Sanford ... Apr. 14—166
Ingenious tooling solves tough milling problems. E. Disco ... Sept. 29— 98
Low-voltage magnetic holding for milling on magnetic chucks. Axel Anderson ... May 12—127
Magnetic holding for face milling (cover) ... May 12— 2
Making special cutters for odd milling jobs. L. B. Williams (P.I.) ... Aug. 4—133
Miller grinds tools. Eduard Gast ... Apr. 28—127
Milling screw slots. Dick Bramberg (P.I.) ... Nov. 10—172
Milling a 30-ton diesel main-frame at Cooper-Bessemer (cover) ... Dec. 8— 2
Molding blades milled to shape with special workholder. Martin Heinrich ... Feb. 4—106
New processes . . . will machine the "unmachinable" (table) ... Mar. 17—130
Precision cutoff attachment. Walter Lackner (P.I.) ... Sept. 15—162
Progressive radius milled by key-shaft guided cutter. Eugene Winkler (P.I.) ... Nov. 10—170
Slitting attachment works on miller table. F. C. Lurz (P.I.) ... Feb. 18—167
Turret slide and miller cuts cams. Allan Clarke (P.I.) ... Mar. 17—154
Vertical miller cuts half sphere. Gerhard Wenke (P.I.) ... Feb. 4—130
Vertical milling attachment does light, accurate work. D. J. Unwin (P.I.) ... Apr. 28—130
What's what in miller vibration (charts & tables) ... Sept. 15—176
Workholding endmill. Hasm Murro (P.I.) ... Oct. 13—171
Models—Ford plasticale prototypes speed tooling. Rupert Le Grand (report) ... May 12—159-164
Modernization—General Electric offers "progressive modernization" program ... May 26—136

Molds and Molding:
Cams drive small cores in an injection mold. G. H. DeGroat ... June 23—110
Hot molding increases scope of powder metallurgy. J. F. Kuzmick ... July 7—132
Mold-gate design eliminates trimming. Cliff Bossman (P.I.) ... Sept. 29—130
Plastics—equipment and technique. D. A. Dearle (report) ... Apr. 28—107-122
Plow mold boards' press-formed to shape. Oscar Nelson ... June 9—122
Racks and pinions drive plastic mold cores. G. H. DeGroat ... Apr. 28— 97
What's ahead the next ten years in casting and molding ... Mid-Nov. section B
Molybdenum disulphide—how to use it as a lubricant. L. M. Davison (charts) ... Dec. 22—106
Monorails, cranes and hoists ... Mid-Nov. section J10
Motors—Portable-drill motor subs for gear motor. Pablo Redl (P.I.) ... Jan. 7—156
Small DC motor runs lapping setup. G. T. Miller (P.I.) ... Aug. 18—131

Munitions:
American Machinist Metalworking Facts for 1952 (charts & tables) Jan. 21—129-144
Cartridge cases are drawn from hot-gorged cups. G. H. DeGroat ... Sept. 15—151
Coining controls thickness and location of shell flange ... May 26—106
How modern gun-drilling improves bolt-making. W. M. Stocker Jr. (report) ... May 26—109-116
New investment casting foundry features latest techniques. Maj. J. T. Andrews Jr. ... Jan. 7—128
Special setups speed production of 20-mm AP shot. F. N. Beede ... July 21—112

N

National Machine Tool Builders' Assn. Fall meeting—progressive decontrol of machine-tool industry advocated Nov. 24—174
Studies domestic and foreign problems ... May 12—192
National Metal Congress List of exhibitors ... Oct. 13—208
Racks up big attendance not so much big news ... Nov. 10—184
Show in print ... Oct. 13—192
National Metal Show, Philadelphia. New developments, machines draw big crowds ... Oct. 27—159
National Production Authority Inventory program puts idle machine tools to work ... July 7—182
M-41 amended to allow shipment of unrated machine-tool orders ... Aug. 4—150
National Tool & Die Mfrs Assn. Series
Adjustable cams time bending. G. H. DeGroat ... June 9—155
Cams drive small cores in an injection mold. G. H. DeGroat ... June 23—110
Compound dies blank, pierce, and form multiple parts. W. M. Stocker Jr. ... July 21—104
Grinding fixture aids die manufacture. Rupert LeGrand ... Nov. 24—134
How to keep .2" 0.0002-in. accuracy throughout press operations. Rupert LeGrand ... May 12—132
Racks and pinions drive plastic mold cores. G. H. DeGroat ... Apr. 28— 97
Sectional dies are easier to finish. B. C. Brosheer ... Mar. 3—161
7th annual meeting talks automation, human relations ... Nov. 24—179
6-stage progressive die forms heavy stock ... Aug. 18—112
Timed press tools make and assemble three parts. Rupert LeGrand ... Feb. 4— 95
Tricky tooling stamps on stamping costs. M. J. Rowan ... Feb. 18—138
Nickel—Development of nickel ... Mid-Nov. section A9

Noise:
Checking noisy machinery. Fred Lettino (P.I.) ... July 21—127
Noise . . . a shop problem (report) ... Dec. 22—109-116
Wood stock tubes cut shop noise. N. Palmer (P.I.) ... Aug. 4—130
Nuts—Coil-winder speed nut has lever control. William Richter (P.I.) ... Aug. 14—178

O

Office of Price Stabilization Gives rules on pass-along increases ... Sept. 29—148
Revision simplifies pricing ... Aug. 18—134
Olinizing—close control in plating and wet blasting before and after eliminates regrinding and break-in ... Oct. 13—158
Olympia Exhibition, London—Letter from the editor. Burnham Finney ... Sept. 29—144
... Oct. 13—182
Optical instruments—Smart tooling solves tough elliptical boring job. S. D. Phillips ... Dec. 8—140
Optical measuring—Collimator and how to use it. R. F. Mitchell ... Nov. 10—161
Optical tools ... Mid-Nov. section C9

P

Paints and painting Organic coatings ... Mid-Nov. section H2
Paley Report—Public airing ... Dec. 8—162
Pawls for business machines made more accurately by powder metallurgy (chart) ... Oct. 13—126
Peening—Control of shot peening Pts 1, 2 & 3 (Ref. Bk. Sheets) ... Apr. 28—133
Pensions—Cleveland survey of shop pensions ... Apr. 14—162-164
Piercing—Pierce, draw hollow steel forgings to 13 tons ... Aug. 4—146
Piercing die for heavy stock. Federico Strasser (P.I.) ... Dec. 22—120

Pins:
How to design diamond pin locators. E. J. LaBroad (chart) ... Dec. 8—108
Jack pin registers press stock. Donald Zuerl (P.I.) ... Apr. 14—176
Make shear pins shear. S. V. Worth (P.I.) ... Oct. 13—170
Off-center pins mark centerdistances. P. E. Myers (P.I.) ... June 23—124
Pin holder grips screws. O. V. Howe (P.I.) ... June 9—164
Pin measurement of face gears. Silvagi & Francis (Ref. Bk. Sheets) Pts 1, 2 & 3 ... May 12—183
Pin measurement tables for involute gears. R. E. Rawling (Ref. Bk. Sheets) Pts 1 & 2 June 23—133; Pts 3, 4 & 5 July 7—165; Pts 6, 7 & 8 July 21—133; Pts 9 & 10 Aug 4—137
Pin pivots cross-slide for generating radii. A. B. Harvest (P.I.) ... Apr. 28—129
Taper pins handles. H. J. Gerber (P.I.) ... Sept. 15—164

Pipes:
Pipe makes rugged boring bar. J. T. McCafferty (P.I.) ... Nov. 24—161
Pipe taps electrically etched. R. V. Kendall (P.I.) ... Apr. 28—129
Pipe threads. Elmer Zeuk (Ref. Bk. Sheets) (charts & tables) Pts 1, 2 & 3 Nov. 10—177; Pts 4, 5 & 6 Nov. 24—167

Planers:
Bridged templet guides radius-cutting planer. R. J. Rossi (P.I.) ... Apr. 14—177
Planer fixture bends bolts. Stanley Hodge (P.I.) ... Mar. 31—120
Planing and shaping developments ... Mid-Nov. section E18

Plant Layout:
Better handling saves building space. J. E. Wiltrakis ... Dec. 8—136
Conveyors and convenience cut switch-assembly costs at McGill Mfg. Co. M. C. Carlson ... May 12—136
How Ford plans for low-cost chip handling. M. J. Rowan (charts) ... Apr. 14—134
How Sperry harnesses the electron. E. J. Tangerman (report) Apr. 14—143-157
Northrop Aircraft's plant-layout checkerboard ... Dec. 8—161
"Shop in stockroom" provides point-of-use storage. M. J. Rowan ... Feb. 4—124
Plant location—Industry locates plants away from cities ... Apr. 14—195
Plant services—What's ahead the next ten years in plant services ... Mid-Nov. section J

Plants:
Growing use of adjustable-speed drives prompted new Reliance Electric plant ... June 9—179
Industrial plant expansion for specific defense items needed ... Aug. 4—148
Industry's plans for plant expansion in '52 will be pared ... Mar. 3—201
Tool builder, grabbed by Russians, sets up shop in West ... July 21—143

Plastics:
Developments in plastics ... Mid-Nov. section A11
Low-cost methods speed zinc, plastic and steel die construction. W. C. Miller ... Dec. 8— 93
Men of "parts" watch machines work at Sylvania. Tangerman & DeGroat (report) ... Sept. 15—113-136
Plastic models make inspection crystal clear ... July 21—140
Plastic supply out of danger ... Jan. 7—212
Plasticale prototypes speed Ford tooling. Rupert LeGrand (report) May 12—159-164
Plastics—equipment and technique. D. A. Dearle (report) ... Apr. 28—107-122
Racks and pinions drive plastic mold cores. G. H. DeGroat ... Apr. 28— 97
Reinforced plastics—a look to the future ... July 21—214

Plates:
Drill-press jig reproduces holes in dividing-head plate. H. J. Gerber (P.I.) ... May 26—120
Electroplating ... Mid-Nov. section H4
How to set up a heavy angleplate. Thomas Gray (P.I.) ... Oct. 13—169
How to work with beryllium-copper strips. J. T. Richards (charts & tables) ... Mar. 31—99-114
Knurling ups wear resistance of chrome plate. E. F. Disco ... Aug. 4—101
New plating process demonstrated at American Electroplaters' Society show ... July 7—182
Reducer pusher-plate wear. David Bruce (P.I.) ... Nov. 24—162
Regrind and break-in blasted from chrome-plated tools ... Oct. 13—158
Simple, rugged index plate does universal holding jobs. N. Palmer (P.I.) ... Aug. 18—134
Tilting angle plate holds small angles. G. D. Carlsen (P.I.) ... Apr. 28—129
Two chucking faceplates hold work on center. N. Palmer (P.I.) ... June 23—125
Plugs—Step in gage fixture aligns locating plug. F. A. Adams (P.I.) ... June 9—163
Polishing—How to electro-polish stainless steel. Samuel Storchheim ... May 12—140
Polishing ... Mid-Nov. section H6

Powder Metals:
Hot molding increases scope of powder metallurgy. J. F. Kuzmick ... July 7—132
Ingenious tools make complex metal-powder parts. G. H. DeGroat Sept. 1—105
Methods of production metal parts ... Mid-Nov. section B6
Parts of powder-metal save ordnance $2 million ... May 26—191
Re-set pawl tolerances held by powder metallurgy (chart) ... Oct. 13—126
Spray and sinter to make high temperature alloy parts. Cline, Thurston & Wolff ... Mar. 3—172
Power—building services ... Mid-Nov. section J
Practical ideas from popular departments ... Mid-Nov. section K

Presses:
Accessories for OBI presses (Ref. Bk. Sheets) ... Oct. 13—179
Adjustable press cutoff tool. Miller Hough (P.I.) ... Jan. 7—*152
Air Force orders 20 giant presses to boost production ... Feb. 4—144
Bed dimensions for OBI presses (chart) (Ref. Bk. Sheet) ... Sept. 1—151
Big, busy press—Babcock & Wilcox 6500-ton hydraulic press (cover) ... Oct. 13— 2
Bliss welds heavy presses for aluminum forging program ... Sept. 29—147
Compound dies in presses blank, pierce, and form multiple parts. W. M. Stocker Jr. ... July 21—104
Dodge automates press forging. Rupert LeGrand ... Sept. 29—123
Don't overlook operator safety in press-tool design. L. A. Faulkner (report) ... Sept. 1—121-136
Edge-bending kickup press ... Sept. 29—145
Four feeds automatize punch press. Matson & King ... Jan. 7—132
Gate guards give greater press safety. R. F. Thuma ... July 7—130
Guide-strip takeup counteracts width variations. Howard Morgan (P.I.) ... Mar. 31—121

(ed) Editorial (P.I.) Practical Ideas

Hot molding increases scope of powder metallurgy J. F. Kuzmick July 7—132
How to keep ±0.0002-in. accuracy throughout press operations Rupert LeGrand May 12—132
Inclined jack in registers press stock Donald Zuerl (P.I.) Apr. 14—176
Ingenious tools make complex metal-powder parts G. H. DeGroat Sept. 1—105
16 open-back inclinable presses (Ref. Dk Sheets) (charts) Aug. 4—141
Latest improvement in press automation at Ford M. J. Rowan (report) Dec. 8—109-118
Martin, Glenn L. Co. shop shots Aug. 4—102
Multiple bending multiplies production T. M. Rybarczyk Feb. 4 *100
Plastics—equipment and technique. D. N. Dearle (report) Apr. 28—107-122
Plow mold boards press-formed to shape Oscar Nelson June 9—122
Punching out flash on drillpresses at Yoder Die Casting Aug. 18—130
3 dies in one press (cover) Dec. 22— 2
75,000-ton forging press no longer considered vital to plane output Jan. 7—169
Shear for press tools R. G. Vare (P.I.) Nov. 10—171
Timed press tools make and assemble three parts Rupert LeGrand Feb. 4— 93
Toothed stripper clears feeding stock T. H. Hsu (P.I.) Apr. 28—128
United States Air Force heavy press program takes on firmer shape (table) Dec. 8—158
Watch your language for pressworking Federico Strasser (chart) Sept. 1—136
What's ahead the next ten years in press work and forging Mid-Nov. section D
Will symbols for press tools simplify communications? Federico Strasser (chart) Sept. 1—135

Prices:
American Machinist wholesale price index for machinery Mar. 3—202
Decontrol near for materials, metals, prices May 12—190
Production—Machine-tool productivity rises Aug. 18—133
Never underestimate the power of . . . Burnham Finney Aug. 4— 93

Production Control:
Alco trading assemblies the M-47 hybird E. J. Tangerman (report) Aug. 18—119-126
Automatics roll off the line. E. J. Tangerman Sept. 15—137
Automatic welding makes eyebolts faster, better. W. H. Volkmar Aug. 18—127
Automation triples pail-line output. F. Paquette Dec. 22— 98
Big output of GM refrigerators in Brazil Mar. 3—204
Commission to advise defense on long-range production May 12—191
"Cumulative sampling" boosts shop output 25% C. H. Latter Sept. 29— 95
Curtiss-Wright boosts output with machinability data Rupert LeGrand (report) (tables) Nov. 24—141-148
Extending the worker's ability to produce. Burnham Finney Dec. 8— 91
Fiber ducts save time in wiring machine panels. R. T. Johnstone Dec. 8—105
Ford unveils new engineering set-up; shows production methods Jan. 21 *294
General Electric offers "progressive modernization" program May 26—136
Germans enjoy machine-tool boom, spurred by western rearmament Apr. 14—194
Harness assembly can be a production job—Sperry Gyroscope (cover) Apr. 14— 2
How Ford automates production lines Rupert LeGrand Mar. 17—135-150
How Sperry harnesses the electron. E. J. Tangerman (report) Apr. 14—143-157
How to cut overhead costs. D. E. McNeil (charts & tables) (reports) Sept. 29—111-122
How to estimate hobbing time. Johnson & Nolting (charts) Apr. 14—127
Increase machine capacity with control charts. Joseph Manuele (charts) Feb. 18—131
Latest improvements in press automation at Ford. M. J. Rowan (report) Dec. 8—109-118
Lincoln Electric's "shop in stockroom" provides point-of-use storage. M. J. Rowan Feb. 4—124
Low cost methods speed zinc, plastic and steel die construction. W. C. Miller Dec. 8— 93
Make research data useful to the shop man. Dr. M. Kronenberg (tables) Sept. 15—145
Master fixtures assembly troubles. Frank Charity Mar. 31— 92
Men of "parts" watch machines work at Sylvania. Tangerman & DeGroat (report) Sept. 15—113-136
Midmarch Machine, Sidney, Ohio, revamps production line, adds new plant for T-lathe Nov. 10—187
No room for complacency. Burnham Finney July 21— 97
Noise . . . a shop problem (report) Dec. 22—109-116
One horn card controls all tools. Walter Hubbell Apr. 14—170
Plant-wide planning stretches new-equipment dollars. M. J. Rowan Mar. 17—119
Production equipment not yet idle, but steel supply worsens July 21—144
Productivity doesn't go up automatically. Burnham Finney Sept. 29— 93
Rescheduling shop-loading plan at Northrop Aircraft flattens zig-zag production curve. D. R. Hutsh July 7—137
Simple zinc-alloy dies speed small orders. J. A. Thomson July 7—138
"Slow kinks" boost output at Douglas Aircraft W. A. Nordhoff Aug. 4—108
Special setups speed production of 20-mm AP shot. F. N. Beede July 21—112
Stacked conveyors boost pressline flexibility George Corsi June 9—132
Statistical controls save International Harvester $10 million. M. J. Graham Mar. 3 *153
Tool engineers influence "producibility" June 23—140
Transfer cars keep assembly moving. E. L. Brainard Nov. 10—132
Washington looks behind the boom Oct. 27—161
Welding 240 sq. in. in 30 seconds (cover) May 26— 2

Production Equipment Advisory Committee set up in ODM May 26—134

Pulleys—Pulley drive drills hidden hole. C. C. Boston (P.I.) July 7—160

Pumps:
DeLaval Steam Turbine Co. gang-milling pump casings (cover) Apr. 28— 2
Grease-gun pump. J. C. Salinas (P.I.) Mar. 31—120

Punches:
Cam-controlled punch forms accurate tube H. Morgan (P.I.) Sept. 29—131
Die fillet blocks support thin punch wall. F. C. Elmo (P.I.) July 21—128
Four feeds automatize punch press. Matson & King Jan. 7 *132
Hole punch for thin-walled tubing. Piero Widmus (P.I.) Dec. 22—121
Punch table simplifies notching. Pablo Redl (P.I.) Mar. 17—155
Punching out flash on drillpresses Aug. 18—130
Reinforced punch walls. F. C. Elmo (P.I.) Sept. 1—141
Rotating punch bends small rings. Hjalmar Dahl (P.I.) June 9—164
Rubber punch cuts lead foil. T. H. Hsu (P.I.) Aug. 4—152
Small dies . . . lots . . . cost. Evert Blomgren Feb. 4—108
Soluble oil lubricates punches. Federico Strasser (P.I.) May 12—178
Tapered punch cuts holes in belting. D. D. Arnson (P.I.) Aug. 18—132
Washer punch. Hermann Voss (P.I.) Sept. 15—163

Quality Control:
How modern gun-drilling improves hole-making. W. M. Stocker Jr. (report) May 26—109-116
How Sperry harnesses the electron. E. J. Tangerman (report) Apr. 14—143-157
How to keep ±0.0002-in. accuracy throughout press operations. Rupert LeGrand May 12—132
Increase machine capacity with control charts. Joseph Manuele (charts) Feb. 18—131
Men of "parts" watch machines work at Sylvania. Tangerman & DeGroat (re-alloys Harkins & Thompson Dec. 8—119
Plastics make inspection crystal clear July 21—140
Precision contour grinding makes better tools F. C. Victory Sept. 15—113-136
Novel methods are weld high-strength Pt. 1 Sept. 15—154
Pt. 2 Sept. 29—106
Quality control Mid-Nov. section I 5
Recording voltmeter checks weld quality. G. A. Hatfield Apr. 14—158
Reset pawl tolerances held by powder metallurgy (chart) Oct. 13—126
Statistical control saves International Harvester $10 million. M. J. Graham Mar. 3—153

Racks—Bandsaw storage rack made from 2x4's. Charles Schwartz (P.I.) July 7—161

Radii:
How to mill a large radius. E. Winkler (P.I.) Oct. 13—170
Pin pivots cross-slide for generating radii. A. B. Harvest (P.I.) Apr. 28—129
Progressive radius milled by key-shaft guided cutter. Eugene Winkler (P.I.) Nov. 10—170
Simple fixture turns many radii. Donald Watson (P.I.) Dec. 22—121

Radio tubes—Tricky loading turns out tubes. Tangerman & De Groat June 23— 97

Radioactivity—Practical results from radioactive tracer studies of tool life. Aug. 18—108

Ratio determines depth of thread chasing feed. W. R. Kampe (P.I.) Dec. 8—143

Reamers and Reaming:
Boring tools made from old drills and reamers. G. J. Van Hecke (P.I.) Mar. 17—157
Emergency reamer practices. R. C. Hoard Jan. 7—147
How to drill, ream and tap titanium alloys Mar. 3—141
Reamer alignment counteracts table-to-dexing errors. W. S. Jaro (P.I.) Feb. 18—166
Reamer-centering collar improves accuracy. O. W. Anderson (P.I.) Feb. 18—166
Shims enlarge hole tools. Rudy Martinka (P.I.) Apr. 14—177
We buy tools from past performance. J. M. Finally Apr. 14—174

Reference Book Sheets
Jan. 7—159, Jan. 21—175, Feb. 4—137, Feb. 18—173, Mar. 3—195, Mar. 17—161, Mar. 31—125, 129, Apr. 14—183, 185, 187, Apr. 28—133, May 12—183, May 26—127, June 9—169, June 23—131, 133, July 7—165, July 21—133, Aug. 4—137, Aug. 18—137, Sept. 1—147, Sept. 15—169, Sept. 29—137, Oct. 13—173, 179, Oct. 27—181, 155, Nov. 10—177, Nov. 24—167, Dec. 8—149, Dec. 22—127
Group of typical Reference Book Sheets Mid-Nov. section K 35

Refrigerators—Big output of GM refrigerators in Brazil Mar. 3—204

Research:
Allegheny Ludlum Steel opens research lab for metals investigation Dec. 8—157
Europe studies carbide cutting. E. J. Tangerman Feb. 18—134
Make research data useful to the shop man. Dr. M. Kronenberg (tables) Sept. 15—145
Special duplicators speed experimental jet-engine blades. M. J. Rowan Mar. 3—166

Rings:
Rings hung up for upside-down turning Oct. 27—113
Rotating punch bends small rings. Hjalmar Dahl (P.I.) June 9—164
Snap-ring guide speeds assembly. Mario Gaweke (P.I.) Apr. 28—126
Three dies form 1-in. rings. T. H. Hsu (P.I.) Aug. 4—133
Two operations form full ring. F. M. Buttrick Jr. (P.I.) Sept. 29—133
Two operations to form rings. A. Vetsch (P.I.) Nov. 10—172

Rivets and riveting—Drillpress adapter peens rivet heads. Donald Watson (P.I.) Aug. 18—133
What's ahead the next ten years in joining and assembly Mid-Nov. section F

Rods—Collect punched blanks. Haim Murro (P.L.) Nov. 10—173

Rolls:
How to roll back forming costs. A. F. Schuh Mar. 17—152
Off-center V-roller clamps odd-shaped part. Jack Jensen (P.I.) Mar. 3—179
Rubber roller clears saw chips. J. T. Smith (P.I.) July 21—128
Superfinishing a mill roll at American Steel & Wire Co. (cover) June 9— 2

Round table
Jan. 7—151, Jan. 21—115, Feb. 4—123, Feb. 18—163, Mar. 3—181, Mar. 17—151, Mar. 31—115, Apr. 14—165, Apr. 28—123, May 12—172, May 26—117, June 9—160, June 23—121, July 7—155, July 21—123, Aug. 4—127, Aug. 18—128, Sept. 1—137, Sept. 15—161, Sept. 29—127, Oct. 13—157, Oct. 27—141, Nov. 10—163, Nov. 24—157, Dec. 8—139, Dec. 22—117

Russia:
Iron curtain lifts to reveal Russian machine tools Dec. 8—131
Never underestimate the power of . . . Burnham Finney Aug. 4— 93
Soviets set new 5-year plan goals Sept. 1—156

Rust preventive—Solid-film lubricant coatings applied by Friden Calculating Machine. Fred Shear Sept. 29—128
Special dip routine bans weekend rust Feb. 18—142

Ryan Aeronautical Co. shop shots Aug. 4— 103

(ed) Editorial (P.I.) Practical Ideas

S

Safety:

Be sure your machine tools are electrically safe ... June 9—147
Don't overlook operator safety in press-tool design. L. A. Faulkner (report) ... Sept. 1—121-136
Drillpress safety plug and chuck wrench. Thomas Trail (P.I.) ... Feb. 18—167
Gate guards give greater press safety. R. E. Thoma ... July 7—130
Grinder safety brake. Haim Murro (P.I.) ... Sept. 15—164
How Oak Ridge machines beryllium. Case & Watkins ... Dec. 22— 93
Keeping weak links out of safety. Chain Belt Co. safety program. A. W. Bathke ... Dec. 8—134
Off-the-job accidents cost $3 billion a year. A. S. Johnson ... Oct. 13—148
Safe handling of magnesium (Ref. Bk. Sheets) Pts 1 & 2 ... Sept. 1—147
Shaper clip shield. Maurice Conklin (P.I.) ... Feb. 18—168
Signal light monitors air mechanisms. W. T. LaLond ... Feb. 4—132
Solar Aircraft's "doghouse" pens up plant housekeeping ... Sept. 15—160
Sorry you're not covered—fire insurance. W. W. McCall ... Nov. 24—158
Salvage—How form tools salvaged by regrinding. A. E. Salmons (P.I.) ... July 21—130
Sandwich—"Hot copper sandwich" may boost jet performance ... June 9—157
Sandwich structures are simple ... May 26—118

Saws and Sawing:

Bandsaw slotting fixture. T. H. Hsu (P.I.) ... Sept. 1—143
Belt and buckle power-feed saw. Harold Goldstein (P.I.) ... Mar. 31—122
Hacksaw blade saver. Thomas Trail (P.I.) ... Oct. 13—169
How to get the most out of bandsaw blades. H. J. Chamberland ... Feb. 18—164
Labor is the big factor in friction-sawing costs ... Sept. 15—153
Rubber roller clears saw chips. L. T. Smith (P.I.) ... July 21—128
Slitting attachment works on miller table. F. C. Lutz (P.I.) ... Feb. 18—167
Small dies — bits — costs. Evert Blomgren ... Feb. 4—108
Scales—Roll-on platform scale. Pablo Redl (P.I.) ... Sept. 29—132

Scrap:

Don't scrap HSS. B. A. Rogers ... Jan. 7—152
Obsolete tools, dies, jigs and fixtures ... Mar. 17—172
Scrap price is up but supplies are good ... Sept. 1—159

Screw Machines:

Automatics roll off the line. E. J. Tangerman ... Sept. 15—137
Carbide insert stops swing-stop wear. O. V. Howe (P.I.) ... Sept. 1—143
Stenciling attachment works on screw machine. D. A. Rogers (P.I.) ... Mar 3—179

Screws:

Adjustable boring bar swivels on set-screws. J. C. Salinas (P.I.) ... Mar. 3—176
Emergency transfer screws. Joseph Mate (P.I.) ... Nov. 24—163
Jackscrew die-lifter. M. M. McKenzie (P.I.) ... Sept. 1—142
Milling screw slots. Dick Branberg ... Nov. 10—172
Nut-clamp grips screw for cut-off. C. T. Bower (P.I.) ... Sept. 29—132
Pin holder grips screws. O. V. Howe (P.I.) ... June 9—164
Progress in bolts and screws ... Mid-Nov. section F— 7
Screw jig simplifies cutoff. F. M. Butrick Jr. (P.I.) ... May 26—120
Screw thread decarburization limits (Ref. Bk. Sheets) ... Apr. 14—185
Scribers—Scribing circles on castings. T. J. Pech (P.I.) ... Apr. 14—180
Stop scriber-pad loss. W. A. Sauer (P.I.) ... Oct. 13—172
Scaling—How to seal porous castings. Pts 1 & 2. M. J. Nathanson (Ref. Bk. Sheets) ... Jan. 7—161
Shafts—Geared shafts milled in pairs. R. G. Vare (P.I.) ... July 7—161
How Studebaker makes a crankshaft. Foreman & Mishler ... Mar. 3—156

Shapers:

Hand-controlled shaper grinds cutters. Max Karfunkel (P.I.) ... May 12—179
Machining angles on the shaper. Prof. M. F. Spotts (Ref. Bk. Sheets) ... Jan. 7—159
Planing and shaping developments ... Mid-Nov. section E 18
Shaper clip shield. Maurice Conklin (P.I.) ... Feb. 18—168
Shaper swivel and tool cut radii and curves. A. T. Renson (P.I.) ... May 12—180
Simple mechanism increases gear-shaper capacity. O. F. Lambert (P.I.) ... Sept. 1—140

Sharpening—Gage your hob sharpening and save tools. B. C. Brosheer ... Aug. 5— 95

Shears and Shearing:

How to shear to closer limits. J. J. Murphy ... May 26—102
Make shear pins shear. S. V. Worth (P.I.) ... Oct. 13—170
Shear for press tools. R. G. Vare (P.I.) ... Nov. 10—171
Shear mechanism on die works every eleventh stroke. Albert Lensky (P.I.) ... May 26—171
Shimstock—Cheaper than micrometers. C. D. Carlsen (P.I.) ... Dec. 22—121
Shop shots ... Jan. 7 *148, Mar. 17—134, Apr. 28—100, June 9—158, June 23—122, Aug. 4—102, Aug. 18—144, Sept. 15—158, Nov. 10—166, Dec. 22—118
Shops—Tool and die shop expansion pushed by heavy defense volume in Los Angeles ... Feb. 18—184
Sine bars—Multiple work done by two bars (P.I.) ... Aug. 4—131
Simple sine bar sets grinding angles. R. G. Vare (P.I.) ... July 7—162
Sintering—Spray and sinter to make high temperature alloy parts. Cline, Thurston & Wulff ... Mar. 3—172
Sizing—Ingenious tools make complex metal-powder parts. G. H. DeGroat ... Sept. 1—105
Slides—Round bar stock makes inexpensive machine slides. C. T. Bower (P.I.) ... Aug. 4—130

Slotters and Slotting:

Hand tool slotting. G. H. Sheppard ... Feb-4—109
Bandsaw slotting fixture. T. H. Hsu (P.I.) ... Sept. 1—143
Power feed slots shafts in lathe setup. Tom Brown (P.I.) ... June 23—128
Slotting fixture load rapidly. B. P. Fortin Sr. ... Apr. 28—102

Social Security—Self-employed must now pay social security tax ... Mar. 3—204

Solder and Soldering:

Flame-fluxing with brass brazes high-strength assemblies. John Shinn ... Nov. 24—133
How to work with beryllium-copper strip (charts & tables). J. T. Richards ... Mar. 31—99-114
Short-run dies are soldered together. Howard Morgan (P.I.) ... Feb. 18—168
Wooden soldering clamps set up corners. C. T. Bower (P.I.) ... Sept. 1—141

Solenoids—Welding speeds solenoid production ... Oct. 13—125

Sound waves—Sonic tester checks bonding of honeycomb panels. H. O. Williams ... Sept. 1—116
Spacing—Radial spacing beyond normal jig-borer limits. Dietlin & Stevens (P.I.) ... Dec. 22—123
Spanner—Monkey wrench makes adjustable spanner. C. D. Carlsen (P.I.) ... Dec. 22—123

Speeds:

Adjustable cams time bending. G. H. De Groat ... June 9—155
Braced drill cuts at high speed. N. Palmer (P.I.) ... May 12—176
Cam latch speeds steadyrest loading. O. O. Kilsburn (P.I.) ... Sept. 15—166
CO2 cools tools . . . increases speed. E. J. Tangerman ... Mar. 3—129
Drill speed and feed charts. J. H. Landvater (Ref. Bk. Sheets) Pts 1, 2 & 3 ... Mar. 17—161
High rake angles aid milling performance. Crawford & Merchant ... July 7—172
High-speed milling (cover) .. Aug. 4— 2
How draw speed affects stainless wire. Samuel Storchheim (charts) ... July 21—124
How to run a drillpress—report. H. E. Linsley ... Feb. 18—147-162
Micro-switch makes centrifugal governor. B. Berman (P.I.) ... Dec. 22—120
Nerve and sharp tools machine any stainless at high speeds. E. Von Hambach ... Jan. 7—117
Sigma welding stars on 3 new jobs. Frank Harkins ... Aug. 18—109
Sperry-Gyroscope—How Sperry harnesses the electron. E. J. Tangerman (report) ... Apr. 14—143-157
Spheres—Surplus borer tooled for spheres. Paul Jordan ... Feb. 4 *110
Vertical miller cuts half spheres. Gerhard Wenke (P.I.) ... Feb. 4 *130
Spider for clothes—Drying machine is arc-welded. G. C. Farrington ... Oct. 13 *147
Spinning—Standard roller-turning box modified to spin tube ends. Allen Clarke (P.I.) ... May 12—178
Strengthened engine lathe does tough spinning jobs (P.I.) ... Aug 4—129
Spotfacing—Spotfacer made from old drill. Roger Isetts (P.I.) ... June 9—161
Spraying—Spray and sinter to make high temperature alloy parts. Cline, Thurston & Wulff ... Mar. 3—172
Springs—Clamping die forms round springs. T. H. Hsu (P.I.) ... July 21—127
Stackers—Feeders and retrievers aid lamination blanking. B. C. Brosheer ... June 9—128
Stamets, William K.—Celebrates 40 years in machine-tool industry ... June 9—176

Stamping:

Die construction speeded by low-cost methods. W. C. Miller ... Dec. 8— 93
Latest improvements in press automation at Ford stamping plant. M. J. Rowan (report) ... Dec. 8—109-118
Tricky tooling stamps on stamping costs. M. J. Rowan ... Feb. 18—138

Standardization—Defense Production Administration standardization throws Air Force and Navy into a tizzy ... Aug. 4—149

Standardize purchases with planned abrasive control. C. R. Glenn (charts) ... June 23—102

U.S. industry scored for lack of interest in standards ... July 7—179

Statistical techniques ... Mid-Nov. section I 8

Steel:

Alco steel—chrome glass coating on molybdenum for jet-engine parts ... Sept. 1—109
Bigger allocations to benefit small users ... Apr. 14—190
Bolt-steel classification (tables) (Ref. Bk. Sheets) ... Apr. 14—187
Britain uses 8 new economy steels to save nickel, molybdenum (table) ... Feb. 4—145
Cold-forge stainless handles in mid-air ... Nov. 10—126
Copper strips spotweld stainless. R. G. Vare (P.I.) ... Apr. 14—176
Dam tooling turns out tough steel rollers and tracks for Garrison Dam. Hilton & Shields ... Nov. 24—130
Half-hour test finds copper in steel ... June 23—112
How aluminum banding is keyed to production. W. M. Stocker Jr. ... July 21—108
How to electro-polish stainless steel. Samuel Strochheim ... May 12—140
How to machine and finish stainless steel. Stevens, Banikoski & Spencer (report) (tables) ... Aug. 4—111-126
How to machine stainless steel with carbides. J. J. Robert ... Oct. 27—109
Investment castings need not be "free-machining" stainless. Wood & Von Ludwig (charts & tables) ... Nov. 10—147
Measurement of case depth. James Sorenson (table) (Ref. Bk. Sheets) ... Mar. 31—129
Nerve and sharp tools machine any stainless at high speeds. E. Von Hambach ... Jan. 7—117
Plan seeks to get idle steel into use ... Feb. 18—180
Railroads and smart boat handling insure normal winter ore supply ... Sept. 1—158
Soft steel and ultrasonics machine carbide. G. H. DeGroat ... Sept. 15—141
Steel plate cosmotron "doughnut" magnet is 288 shop-made sandwiches ... Nov. 10—128
Steel-strike impact on defense work snowballs as reserves dry up. Aug. 4—144
Steel supply worsens ... July 21—144
Sub-zero hand-tool failures suggest new steels and treatments. Sam Tour (tables) ... Nov. 24—154
Welded-steel lathe bed for seagoing lathe ... Mar. 31—116
Why we now make better stainless steel. J. J. Heger (charts & table) Oct. 13—119

Stenciling attachment—Works on screw machine. D. A. Rogers (P.I.) ... Mar 3—179

Stockroom:

Bandsaw storage racks made from 2x4's. Charles Schwartz (P.I.) ... July 7—161
Maybe you have toolcrib trouble, too! Robert Galloway ... June 9—152
One basic card controls all tools. Walter Hubbes ... Apr. 14—170
"Shop in stockroom" provides point-of-use storage. M. J. Rowan ... Feb. 4—124

Stops:

Correction stop for blanking die. Federico Strasser (P.I.) ... Dec. 22—122
Faceplate stops speed boring work. Lauri Ayala (P.I.) ... Apr. 14—178
Multiple depth stop for drillpress. Anthony Egle (P.I.) ... Dec. 22—123
Stops for dies. Peter Balsells (Ref. Bk. Sheets) Pts 1, 2 & 3 ... Dec. 8—149
Better handling saves building space. J. E. Wiltrakis ... Dec. 8—136

(ed) Editorial (P.I.) Practical Ideas

Storage—see Stockroom

Subcontracting news
Jan. 7—215; Jan. 21—313; Feb. 4—191; Feb. 18—229; Mar. 3—251; Mar. 17—219; Mar. 31—185; Apr. 14—239; Apr. 28—191; May 12—197; May 26—139; June 9—182; June 23—145; July 7—183; July 21—147; Aug. 4—152; Aug. 18—156; Sept. 1—160; Sept. 15—184; Sept. 29—149; Oct. 27—162; Nov. 10—191; Nov. 24—181

Switches:
Chuck wrench keys lathe switch. Roger Marsh (P.I.) Feb. 4—130
Conveyors and convenience cut switch assembly costs at McGill Mfg. Co. M. C. Carlson May 12—136
Micro-switch makes centrifugal governor. B. Berman (P.I.) Dec. 22—120
Switch adjustment controls tuning. Louis deL. Berg (P.I.) May 12—173
Symbols—Will symbols for press tools simplify communications? Federico Strasser (chart) Sept. 1—133

T

Tables—Punch table simplifies notching. Fabio Redl (P.I.) Mar. 17—153
Six-station table is easily built. J. C. Salinas (P.I.) Mar. 17—157
Two-position drill table saves space, ups accuracy. A. V. Jensen Aug. 18—114
Talented tooling Jan. 7 *126; Apr. 14 *132
Tanks—How to cool oil-quench tanks. C. L. Ringquist Aug. 18—106
Peroxide tanks pose welding problems. W. F. Shefelton Apr. 14—171

Tanks (Military):
Also tooling assembles the M-47 hybrid. E. J. Tangerman (report) Aug. 18—119-126
American Locomotive Company—M-47 (cover) Aug. 18 2
Army okays M-47 medium tank Apr. 28—141
General Ford tells the ordnance story Aug. 18—146
Tanks roll on welded wheels. Lawrence Maas June 23—106

Tapering:
Belt grinding tapers wing skins. J. R. Burns Sept. 1—154
Die-filing jaws hold taper accuracy. Federico Strasser (P.I.) Mar. 3—179
Taper turning tool tailstock guided. C. T. Bower (P.I.) Aug. 18—132

Taps and Tapping:
Drill chuck drives taps. O. F. Lambert (P.I.) Sept. 1—142
Expansion tap. Abram Hill (P.I.) Oct. 13—173
Extracting a broken tap. C. R. Gladding (P.I.) Aug. 4—134
Friction tap driver has tightness adjustment. N. Bonamini (P.I.) Mar. 31—119
How to drill, ream and tap titanium alloys Mar. 3—141
How to run a drillpress—report. H. E. Linsley Feb. 18—147-162
How and why taps are precision ground. S. W. Lovejoy June 9—135-142
Indicator tapper cuts small threads. F. C. Lurz (P.I.) Jan. 7—184
Modified tapping head chucks odd pieces. Allan Clarke (P.I.) Mar. 3—178
Nut makes tap handle. C. C. Raines (P.I.) Feb. 18—169
Pipe taps electrically etched. R. V. Kendall (P.I.) Apr. 28—139
Precision tapping setup produces accurate nuts. C. Y. Lee (P.I.) Feb. 4—131
Shims enlarge hole tools. Rudy Mattinka (P.I.) Apr. 14—177
Special tap for brass. O. F. Lambert (P.I.) Oct. 27—148
Sprayed vapor ups tap life and speed. W. M. Stocker Jr. Jan. 7—121
Torque teaches titanium tapping. A. J. Carruthers (chart) Sept. 29—102
Tariffs battle affects metalworking May 26—133
Technology—Machinery and Allied Products Institute forms council for technological advancement to spur industry Aug. 18—151
Temco Aircraft Corp. shop shots Apr. 28—160
Temco Aircraft Corp.—tool talk Nov. 24—136

Templets:
Bridged templet guides radius-cutting planer. R. J. Rossi (P.I.) Apr. 14—177
Special duplicators speed experimental jet-engine blades. M. J. Rowan Mar. 3—166
Springs load cutter that follows templet. R. G. Vare (P.I.) June 9—161

Testers:
Half-hour test finds copper in steel June 23—112
How to design and apply master gears. Fred Bohle (charts & table) Dec. 8—125
Machinability tests prove investment castings need not be "free-machining" stainless. Wood & Von Ludwig (charts & tables) Nov. 10—147
Practical results from radioactive tracer studies of tool life Aug. 18—108
Sonic tester checks bonding of honeycomb panels. H. O. Williams Sept. 1—116
Sub-zero hand-tool failures suggest new steels and treatments. Sam Tour (tables) Nov. 24—154
Test methods for weldments Pts. 1, 2 & 3 (Ref. Bk. Sheets) June 9—127
Tests for welding materials Pts. 1, 2 & 3 (tables) (Ref. Bk. Sheets) June 9—169
What's ahead the next ten years in inspection and testing—Mid-Nov. section I

Threading:
Chase acme threads in one lathe cut. D. Lorimer (P.I.) Oct. 27—147
Developments in threading Mid-Nov. section E-21
Differential threads—discussion. A. Vetsch (P.I.) Mar. 3—177
Friction tap driver has tightness adjustment. N. Bonamini (P.I.) Mar. 31—119
General-purpose Acme screw threads (charts) (Ref. Bk. Sheets) Pts. 1, 2 & 3 Aug. 18—137
Indicating tapper cuts small threads. F. C. Lurz (P.I.) Jan. 7—184
Internal thread guide. J. T. McCafferty (P.I.) Nov. 24—163
Metric threads cut without special gears. Adolph Harvest (P.I.) Mar. 3—177
Multiple-cutting finishes multiple threads. Ben Goodwin (P.I.) Feb. 18—170
Non-standard threading dies. Neville Palmer (P.I.) Nov. 24—162
Pipe threads. Elmer Zook (Ref. Bk. Sheets) (charts & tables) Pts. 1, 2 & 3 Nov. 10—177; Pts. 4, 5 & 6 Nov. 24—167
Plastic threads cut by grinding. J. O. Writ (P.I.) Mar. 3—178
Ratio determines depth of thread chasing feed. W. R. Kampe (P.I.) Dec. 8—143
Screw-thread decarburization limits (Ref. Bk. Sheets) Apr. 14—185
Setup block controls threading tool angle. L. H. Combs (P.I.) July 7—158
Time and motion study—Extending the worker's ability to produce. Burnham Finney Dec. 8—91
How to cut overhead costs. D. E. McNeil (report) (charts & tables) Sept. 29—111-122
Tin—Copper and tin stocks look much better Sept. 1—158
Tips for shop men Jan. 7—120; Feb. 4—107; July 7—136; Aug. 18—105; Sept. 1—112; Sept. 29—97; Oct. 13—165; Nov. 10—169; Mid-Nov. section K
Tips for shop men Mid-Nov. section K

Titanium:
Conference covers problems, sets base for industrial research Oct. 27—160
Growth of the metal Mid-Nov. section A8
How Ryan hot forms titanium Jan. 7—125
How to drill titanium alloys Mar. 3—141
How to grind titanium. Dr. L. P. Tarasov (report) (charts & tables) Nov. 10—135-146
How to weld titanium. (tables) Rosenberg & Hutchinson May 26—93
How we weld titanium. Rohr Aircraft Corp. T. R. Bradley Oct. 13—123
Open die forges titanium cones. Bernstein & Nicolera Feb. 18—136
Six tips on drilling small holes in titanium Jan. 21—314
Titanium ground by Lockheed Mar. 3—175
Titanium tests tools, talent Apr. 28—91
Torque teaches titanium tapping. A. J. Carruthers (chart) Sept. 29—102
Welding study—titanium and titanium-alloy sheet (tables) May 26—98
Tolerances—How to control coordinate tolerances. A. L. Levitt Oct. 13—166

Toolholders:
Adjustable holder for "last-word" indicator. H. H. Opanowicz (P.I.) Dec. 8—143
Combination toolholder gages cut-off lengths. F. C. Lurz (P.I.) May 12—178
Cut-off tool holder has no overhang. Max Kartunkel (P.I.) July 21—129
Double-end turret holds many extra tools. F. H. Colvin (P.I.) Apr. 28—127
How to run a drillpress—report. H. E. Linsley Feb. 18—147-162
Multi-purpose toolholder. M. Moran (P.I.) Nov. 24—164
Tool-relief attachment. F. M. Butrick (P.I.) Sept. 29—132

Tools:
American Society of Tool Engineers tool show Mar. 3—210
British Olympia machine-tool show will feature more automatics Aug. 18—150
Establishment of Production Equipment Advisory Committee in Office of Defense Mobilization May 26—134
Letter from the editor—Olympia Exhibition & Hanover Fair. Burnham Finney Sept. 29—144; Oct. 13—182
Order M-105 on electrical standards for tools halted for more study May 26—134
Plans for new Production Equipment Committee will influence defense budget June 9—176
Portable tools developed Mid-Nov. section C7
Small tools developed Mid-Nov. section C11
Ten shop tools do specialized operations. Robert Laimbeck (P.I.) Jan. 7—154
Tool talk from Temco Aircraft Corp. Nov. 24—136
We buy tools from past performance. J. M. Finally Apr. 14—174
What's ahead the next ten years in tools and tooling Mid-Nov. section C
Tractors—Big lends make farm-loader booms. B. C. Brosheer June 23—108

Training:
How Europe looks at apprenticeship. Burnham Finney Nov. 10—117
Simplify employee training with planned abrasive control. C. R. Glenn (charts) June 23—102
The strangers in your plant. Burnham Finney Feb. 18—129
Transmission—Power-transmission equipment in the metalworking industry Mid-Nov. section A17

Trepanning:
Graphite blocks trepanned to save $20 each. Edward Walker Nov. 10—122
Speeds production of deep holes. F. W. Lucht Mar. 31—96
Trucks—Industrial trucks of today Mid-Nov. section J12
Try this plan for industrial truck maintenance. M. A. Lyons Aug. 4—98

Tubing:
Cam-controlled punch forms accurate tube. H. Morgan (P.I.) Sept. 29—131
Hole punch for thin-walled tubing. Pierre Wilmus Dec. 22—121
Men of "parts" watch machines work at Sylvania, Tangerman & DeGroat (report) Sept. 15—113-136
Tube-connected elbows level large fixtures. R. G. Vare (P.I.) Mar. 31—121
Tubes from slugs: 125 extrusions per minute. Frank Charity May 26—100
Tube-turning tool tailstock mounted. Floyd Geltz (P.I.) Sept. 15—162
Wet belt grinding removes stock from stainless steel tubing in 2 minutes. Olton & Dyer Dec. 8—106
Turbines—Giant size, plus accuracy makes hydraulic turbine building tough. G. H. DeGroat Nov. 10—168
Optical comparators simplify inspection of turbine buckets Aug. 4—104
Turbojets—Turret lathes build turbojets Feb. 4 *119

Turning:
Dynamometers for turning tests. E. J. Tangerman Oct. 13—130
Eccentric turning attachment. W. Lewis (P.I.) Sept. 29—130
How to run an engine lathe. H. E. Linsley (report) May 12—143-158
Rings hung up for upside-down turning Oct. 27—113
Simple fixture turns many radii. Donald Watson (P.I.) Dec. 22—121
Standard roller-turning modified to spin tube ends. Allen Clarke (P.I.) May 12—178

U

Ultrasonics—Soft steel and ultrasonics machine carbide. G. H. DeGroat Sept. 15—141
United States Air Force—Heavy-press program takes on firmer shape (table) Dec. 8—158
U. S. Army Ordnance—General Ford tells the ordnance story Aug. 18—146
U. S. Navy—Packard's precision job-lot tooling makes high-speed diesels for the Navy. B. C. Brosheer Nov. 24—149
Qualified welders produce intricate parts. H. J. Bell Mar. 31—94

V

Vacuum-operated equipment aids metalworking. Frank Charity July 21—102
Valves—Old valves do odd machine-shop jobs. Pablo Redl (P.I.) Feb. 4—131

Vibration:
How to balance a machine without an expert with electronic vibration indicator May 12—173
Noise . . . a shop problem (report) Dec. 22—109-116
Reduce machine vibration by mounting cast-iron carriages on steel beds. Dr. Max Kronenberg Sept. 29—101
What's what in miller vibration (charts & tables) Sept. 15—176

(ed) Editorial (P.I.) Practical Ideas

Vises:
Stop jaw creep on cam-lock vise. J. C. Magee (P.I.) Sept. 15—166
Vise hold-down. D. A. Rogers (P.I.) Oct. 13—172
Vise slide traverses wheel dresser. C. H. Drexler (P.I.) Mar. 3—176
Voltmeter recorder checks weld quality. G. A. Hatfield Apr. 14—158

W

Wage Stabilization Board faces trouble in coal, copper and shipbuilding Aug. 18—152

Wages:
Auto workers gained 30c an hr since '48, manufacturing average is 20c Mar. 17—172
Decontrol near for materials, wages, prices May 12—160
Productivity doesn't go up automatically. Burnham Finney Sept. 29— 93
Something for the boys. Burnham Finney Apr. 28— 89
Wear of tools—practical results from radioactive tracer studies of tool life Aug. 18—108
Wear resistance—Carbide inserts take clutch-collar wear Feb. 4— 99

Welding:
Air and ideas make spotwelder automatic. R. P. Roberts Dec. 22—104
Argon arc welds copper bus bars. W. H. Braner Jr. May 12—174
Automatic welding makes eyebolts faster, better. W. H. Volkmar Aug. 18—127
Change from projection welding to arc welding permits simpler design of spider. G. C. Karrington Oct. 13—147
Copper strips spotweld stainless. R. G. Vare (P.I.) Apr. 14—176
Developments in welding Mid-Nov. section F2
Flashwelding 240 sq. in. in 30 seconds (cover) May 26— 2
How to weld titanium. Rosenberg & Hutchinson (tables) May 26— 93
How to work with beryllium-copper strip. J. T. Richards (charts & tables) Mar. 31—99-114
How we weld titanium—Rohr Aircraft Corp. T. R. Bradley Oct. 13—123
Ingenious machines weld thin-wall stainless tanks. R. L. Brown Nov. 24—125
Line welding speeds new armored hulls Oct. 27—120
Navy-qualified welders produce intricate parts. H. J. Boll Mar. 31— 94
Novel methods are weld high-strength alloys. Harkins & Thompson Dec. 8—119
Peroxide tanks pose welding problems. W. F. Shefelton Apr. 14—173
Rings hung up for upside-down turning Oct. 27—113
Sigma welding stars on 3 new jobs. Frank Harkins Aug. 18—109
Solenoid production speeded by welding Oct. 13—125
Spotweld spacing. R. G. Vare (P.I.) Sept. 1—142
Tanks roll on welded wheels. Lawrence Maas June 23—106
Test methods for weldments Pts 1, 2 & 3 (Ref. Bk. Sheets) May 26—127
Tests for welding materials Pts 1, 2 & 3 (tables) (Ref. Bk. Sheets) June 9—169
Triple electrode spotwelds wire guard. Howard Powell June 9—151
Welded lathe tools make flycutters. Allan Clarke (P.I.) Mar. 17—136
Welding stars in aircraft production. F. S. Dreyer May 12—150
Welding study: titantium and titanium-alloy sheet (tables) May 26— 98
Welding thin plates. R. G. Vare (P.I.) Nov. 10—173

Welding Equipment:
Body controlled welding fixture. D. G. Nolle (P.I.) Sept. 1—144
Pushbuttons operate welder. Leo Braun Feb. 18—146
Recording voltmeter checks weld quality. G. A. Hatfield Apr. 14—158
Welding clamps hold beams and irons. Robert Lambcock (P.I.) May 12—177
Welding clamps locate and grip. Alwyn Ward (P.I.) May 12—178
Wheels—Specifications. How to grind titanium. Dr. L. P. Tarasov (charts & tables) (report) Nov. 10—135-146
Wind Tunnels—Pair forging makes giant rotor disks Sept. 1—138

Wire:
Fiber ducts save in wiring machine panels. R. T. Johnstone Dec. 8—105
How draw speed affects stainless wire. Samuel Storchheim (charts) July 21—124
How Sperry harnesses the electron. E. J. Tangerman (report) Apr. 14—143-157
Men of "parts" watch machines work at Sylvania. Tangerman & De Groat Sept. 15—113-136
Straightening Wire. Haim Murro (P.I.) Apr. 14—177
Tricky tooling turns out tubes at Sylvania Electric Products Inc. Tangerman & De Groat June 23— 97

Wrenches:
Chuck wrenches keys lathe switch. Roger Marsh (P.I.) Feb. 4—130
Drillpress safety plug and chuck wrench. Thomas Trail (P.I.) Feb. 18—167
Monkey wrench makes adjustable spanner. C. D. Carlson (P.I.) Dec. 22—123
Simple tool cuts hidden chamfer. R. J. Rossi (P.I.) Dec. 8—143

AUTHOR'S INDEX

ADAMS, F. A. Step in gage fixture aligns locating plug June 9—163
Adams, Jerry S. Standardized die blocks cut tool costs Mar. 31— 87
Adamson, B. L. Internal grinding a large bore Nov. 24—163
Albrecht, A. B. COz cools carbide grinders Dec. 8— 97
Alie, Gerald. Emergency surface grinder Sept. 29—133
Amison, Donald D. Tapered punch cuts holes in belting Aug. 18—132
Anderson, Axel. Low-voltage magnetic holding Mar. 17—127
Anderson, O. W. Reamer-centering collar improves accuracy Feb. 18—166
Andrews, Major John T. Jr. New investment casting foundry features latest techniques Jan. 7—128
Ashburn, Anderson. Why and how: we must conserve diamond bort! Nov. 10—181
Askin, J. M. Carbide toolbit reground only on top Mar. 17—155
Austin, Dr. C. R. Flame hardening mechanite castings May 12—165
Ayala, Lauri. Faceplate stops speed boring work Apr. 14—178

BADGER, THOMAS. How to select a cutting fluid Sept. 1—118
Baldenhofer, R. R. Eight ways to grind machine-tool ways Mar. 31— 88
Ball, W. S. Boring-mill cam follower improves finish, cuts time May 12—176
Balsells, Peter. Stops for dies. Pts 1, 2 & 3 Dec. 8—149
Baltuch, Bario. Strip-coiling fixture makes heat exchangers July 7—159
Bankoski, V., G. J. Stevens & L. F. Spencer. How to machine and finish stainless steel Aug. 4—111-126
Bathke, A. W. Keeping weak links out of safety Dec. 8—134
Beck, John. Sharp pencils Sept. 15—165
Beede, Frederick N. Special setups speed production of 20-mm AP shot July 21—112
Bennet, John B. How to welcome new employees. Pts 1 & 2 Oct. 27—151
Berman, B. Micro-switch makes centrifugal governor Dec. 22—120
Bernstein, Harold & Ernest T. Nicotera Open die forges titanium cones Feb. 18—136
Best, George C. Ball-bearing fixture bends plates Mar. 31—118
Blomgren, Evert. Small dies . . . lots . . . costs Feb. 4—108
Boarts, Lyle R. & Joseph S. Corral. Die quenching precision-forms tough alloys July 7—125
Bohle, Fred. How to design and apply master gears Dec. 8—125
Boll, H. J. Navy-qualified welders produce intricate parts Mar. 31— 94
Bonamini, N. Friction tap driver has tightness adjustment Mar. 31—119
Boosmann, Cliff. Drill bushings act as clamps Oct. 27—148
Mold-gate design eliminates trimming Sept. 29—130
Boston, Charles C. Pulley drive drills hidden hole July 7—160
Boulger, F. W., H. L. Shaw & E. A. Lotta. What constituents affect machinability of gray irons? Oct. 27—122
Bower, Clifford T. Air-cushion for heavy jigs Nov. 24—167
Automatic center lubricator Aug. 18—133
Back-up bars for chucking Oct. 13—171
Depth control for lathe drilling Oct. 27—146
Dial-gage arms aid alignment May 26—122
Nut-clamp grips screw for cut-off Sept. 29—132
Planer and shaper clamp for thin-sheet machining May 12—175
Round bar stock makes inexpensive machine slides Aug. 4—130
Simple stepped parallel blocks Oct. 27—147
Taper-turning tool tailstock guided Aug. 18—132
Wooden soldering clamps set up corners Sept. 1—141
Bowler, James W. Add springs to fixture to get downward clamping (P.I.) Feb. 4—132
Bruce, P. H. & E. B. Fitzgerald. Induction brazes squirrel cage Mar. 17—124
Bradley, J. G. Measure hidden diameters Oct. 27—144
Bradley, Thomas R. How we weld titanium Oct. 13—123
Brage, Olin C. Taper indicator added to tailstock Apr. 14—177
Brainard, E. L. Transfer cars keep assembly moving Nov. 10—132
Branberg, Dick. Milling screw slots Nov. 10—172
Brauer, W. H. Jr. Argon arc welds copper bus bars May 12—174
Braun, Leo. Pushbuttons operate welder Feb. 18—146
Brosheer, Ben C. Big bends make farm-loader booms June 23—108
Feeders and retrievers aid lamination blanking June 9—128
Gage your sharpening and save tools Aug. 4— 95
Packard's precision job-lot tooling makes high-speed diesels for the Navy Nov. 24—149
Sectional dies are easier to finish Mar. 3—161
Brown, Robert L. Ingenious machines weld thin-wall stainless tanks Nov. 24—125
Brown, Tom. Cam clamp clears work quickly May 12—179
Checking steadyrest setups Apr. 14—180
Expanding drill jig takes any bushing size Mar. 3—176
Hinged work loaders save grinder centers Apr. 14—176
Pedal operates grinder tailstock lever Feb. 18—169
Power feed shots shafts in lathe setup June 23—128
Screw-clamped fixture has fast action Mar. 17—154
Bruce, David. Reduce pusher-plate wear Nov. 24—162
Brunberg, Paul E. The story behind COz coolant Mar. 3—130
Buckles, Alden W. Boring-bar brace June 9—164
Budnick, Joseph F. Disk grinder conveyer mass-finishes raw castings July 21—126
Burnley, George F. Guide to dressing Sept. 1—143
Simple angle-dresser Sept. 1—141
Burns, Joseph R. Belt grinding tapers wing skins Sept. 1—154
Burrows, Charles. Special gage blocks get into bores June 23—125
Butrick, Frank M. Jr. Alignment pins locate tailstock for taper June 9—161
Micrometer toolblock shift saves lathe tools June 9—166
Screw jig simplifies cutoff May 26—120
Tool backup braces bit May 26—122
Tool-relief attachment Sept. 29—132
Two operations form full ring Sept. 29—133

CALHOUN, ROBERT R. JR. Ball-bearing V-blocks set up shafts and bars May 12—180
Carlarn, C. D. Monkey wrench makes adjustable spanner Dec. 22—123
Shimstock is cheaper than micrometers Dec. 22—121
Tilting angle plate holds small angles Apr. 28—129
Carlson, Marvin C. Conveyors and convenience cut switch-assembly costs May 12—136
Carruthers, Allan J. Torque teaches titanium tapping Sept. 29—102
Carson, Kenneth J. Clean your files with a piece of scrap aluminum May 26—123
Toolbits scribe for height gage Sept. 1—142
Case, J. M. & E. R. Watkins. How Oak Ridge machines beryllium Dec. 22— 93
Cassel, George. How to gun-drill a fixed work piece Feb. 18—144
Chamberland, H. J. How to get the most out of bandsaw blades Feb. 18—164
Charity, Frank. Hot platen forms magnesium easier Mar. 17—123
How high vacuum aids metalworking July 21—102
Master fixtures master assembly troubles Mar. 31— 92
New stretch-forming techniques Sept. 1—113
Tubes from slugs: 125 extrusions per minute May 26—100
Clark, W. F. Negative rake helps carbide core drills Apr. 28—130
Clarke, Allan. Carbide boring tool for deep holes Nov. 10—171
Convenient clamp for boring bar backfacer Sept. 29—134

(ed) Editorial (P.I.) Practical Ideas

Indicating gage floats on fixture June 9—165
Mandrel on sliding jaw chuck grips work on the ID (P.I.) Feb. 4—114
Modified tapping head chucks odd pieces Mar. 3—178
Partly threaded strap has clamping flexibility July 21—126
Scroll-cutting lathe rig (P.I.) Jan. 7—153
Standard roller-turning box modified to spin tube ends May 12—178
Turret slide and miller cut cams Mar. 17—154
Welded lathe tools make flycutters Mar. 17—156

Cline, James E., Robert T. Thurston & John Wulff. Spray and sinter to make high temperature alloy parts Mar. 3—172
Colvin, Fred H. Double-end turret holds many extra tools Apr. 28—127
Conklin, Maurice. Shaper clip shield Feb. 18—168
Coombs, L. H. Setup block controls threading tool angles July 7—158
Cooper, Alfred M. How will you pick your assistant? Aug. 18—116
Corral, Joseph S. & Lyle R. Boarts. Die quenching precision forms tough alloys July 7—125
Corsi, George. Stacked conveyors boost press line flexibility June 9—132
Coy, C. Improved clamp stops marred work Dec. 22—130
Cranston, Lewis. Lathe doubles as boring mill Nov. 24—156
Crawford, Joe H. & Eugene Merchant. High rake angles aid milling performance July 7—172

DAHL, HJALMAR. Jig bores two holes at once Dec. 8—142
Rotating punch bends small rings June 9—164
Universal clamp adjusts for any height Apr. 14—179
Daskel, George Jr. Look at your diamond wheel dressers Oct. 27—142
Davison, T. M. How to use molybdenum disulphide as a lubricant Dec. 22—106
Dawson, P. Whistle grip extends drill Apr. 14—176
Dearle, Denis A. Plastics—equipment and technique Apr. 28—107-122
Decker, James G. Centering drill jig grips parts securely Aug. 4—129
Flexing chuck jaws grip castings accurately June 23—127
DeGroat, George H. Abrasive belts grind carbide Dec. 8—103
Adjustable cams time bending June 9—133
Cams drive small cores in an injection molder June 23—110
Cartridge cases are drawn from hot-forged cups Sept. 15—151
Giant size, plus accuracy makes turbine building tough Nov. 10—168
Ingenious tools make complex metal-powder parts Sept. 1—105
Racks and pinions drive plastic mold cores Apr. 28— 97
Soft steel and ultrasonics machine carbide Sept. 15—141
DeGroat, George H. & E. J. Tangerman. Men of "parts" watch machines work at Sylvania Sept. 15—113-136
Tricky tooling turns out tubes June 23— 97
del Berg, Louis. Switch adjustment controls timing May 12—175
Denison, John S. Microbroaching Mar. 3—114
Dexter, Frederick S. Welding stars in aircraft production May 12—170
DeVoss, Edwin A. Upset beading die cuts rib time 38% Jan. 21—160
Dietlin, J. & T. F. Steven. Radial spacing beyond normal jig borer limits Dec. 22—123
Dixon, E. Ingenious tooling solves tough milling problems Sept. 29— 98
Knurling ups wear resistance of chrome plate Aug. 4—101
Dizikevich, E. Die-maker's folding square Oct. 27—146
Dodson, R. J. Grinding thin stock Aug. 18—132
Halt screw clamps jaws rapidly July 21—128
Shaving cutter slices brass to width Sept. 1—143
Drevler, C. H. Vise slide traverses wheel dresser Mar. 3—176
Dutcher, J. L. & W. B. Wigton. Contouring with heavy machine tools Oct. 27—114
Dyer, Dr. Hugh N. & Direk Olton. Wet belt grinding speeds production of extruded cylindrical stock Dec. 8—106
Dyson, John M. Brazing flux causes spatter Apr. 28—126

EGLE, ANTHONY. Multiple depth stop for drillpress Dec. 22—123
Elmo, F. C. Die-filler blocks support thin punch wall July 21—128
Equalizing clamp for presswork Nov. 10—172
Reinforced punch walls Sept. 1—141
Epstein, Irving. Cable clamping jig Oct. 27—145
Remote column lock for radial drill Oct. 13—168
Remote throttle control built cheaply, installed quickly Aug. 4—132

FARR, C. P. When and why a special machine? Mar. 17—136
Farrington, G. C. Change spider, save part Oct. 13—147
Faulkner, L. A. Don't overlook operator safety in press-tool design Sept. 1—121-136
Thin grinding wheel forms chip breakers June 23—127
Feiman, E. M. Sightless employees pull their weight Feb. 4—102
Finally, John M. We buy tools from past performance Apr. 14—174
Finney, Burnham. Confidence, not fear, should rule Nov. 24—123
Defense policy that makes sense Sept. 1—103
Doing the impossible Mar. 3—127
The engineer makes a good foreman July 7—121
Extending the worker's ability to produce Dec. 8— 93
How cost conscious are you? May 26— 91
How Europe looks at apprenticeship Nov. 10—117
Letter from the editor Sept. 29—144
Oct. 13—182
Letter from Germany Oct. 27—107
Never underestimate the power of Aug. 4— 93
No room for complacency July 21— 97
On European competition Oct. 13—117
Productivity doesn't go up automatically Sept. 29— 93
The rising German challenge Dec. 8— 98
Sensible plan for guns and butter Mar. 31— 85
Something for the boys Apr. 28— 89
Spending 30-cent dollars for savings May 12—125
The strangers in your plant Feb. 18—139
Time for a new look Dec. 22— 95
Tycoons is the word for it June 9—117
What redesign will do May 17—117
What shortchanged means June 23— 95
What to do about engineers Sept. 15—111
Write-offs should be optional Apr. 14—125
Fischer, A. J. & W. Pilug. Preformed shapes save time and carbide Apr. 28—104
Fitzgerald, E. B. & P. H. Brace. Induction brazes squirrel cage Mar. 17—124
Foreman, Fred D. & Orr F. Mishler. How Studebaker makes a crankshaft Mar. 3—156
Fortin, B. P. Sr. Slotting fixtures load rapidly Apr. 28—102
Francis, Vic & J. Silvagi. Pin measurement of face gears Pts. 1, 2 & 3 May 12—183
Freimark, Leopold. Beam compass supports indicator June 23—128
Frischman, T. A. How to maintain heat treating equipment Oct. 13—135
Fristedt, A. E. & H. M. Multberg. Traversing friction meter checks carriage motion June 9—162
Frommer, H. G. Converting skid boxes for long stock Mar. 31—122
Fromson, Robert E. Retriever unloads die-caster automatically Dec. 22—100
Fry, R. H. Angle blocks made for quick setups May 12—177
Indicator attachment checks extra dimension Mar. 17—157
Inspection gantry provides high reference surface July 7—158
Shop-built bench lathe takes large range of work June 23—124
Truing chuck jaws Mar. 31—121

GABLE, STANBURY R. The right gage at the right time Jan. 7—144
Gabriele, Anthony. Two-station broaching die has inverted stripper plate (P.I.) Feb. 4—134
Galloway, Robert. Maybe you have toolcrib trouble, too! June 9—152
Gardiner, William. Simple modification speeds angular facing Nov. 10—173
Gast, Edward. Miller grinds tools Apr. 28—127
Gauerke, Martin. Snap-ring guide speeds assembly Apr. 28—126
Geltz, Floyd. Tube-turning tool tailstock mounted Sept. 15—162
Gerber, H. J. Drillpress jig reproduces holes in dividing-head plate May 26—120
Grinding-wheel code is permanent identification Aug. 18—132
Taper pins handles Sept. 15—164
Gillespie, J. S. How to conserve carbides Pts. 1, 2 & 3 Jan. 21—275
Gilliam, H. R. Cutter-grinder arbor adjusts for grinds June 23—126
Gladding, C. R. Extracting a broken tap Aug. 4—134
Glenn, Charles R. Planned abrasive control June 23—102
Golstein, Harold. Belt and buckle power-feed saw Mar. 31—122
Goodwin, Ben. Multiple cutting finishes multiple threads Feb. 18—170
Graham, M. J. Statistical controls save International Harvester $10 million Mar. 3 *153
Gray, Thomas. How to set up a heavy angle plate Oct. 13—169
Gurney, C. Richard & John T. Tomicki. Plan your government contracts for profits Jan. 21—298

HAHL, H. Double-bending die set forms small channels Aug. 4—131
Halliday, W. M. Centralizing drill jig has high accuracy Feb. 4—132
Ring chucker centers automatically Apr. 14—178
Round cutter machines counterbores July 7—162
Hansen, Del. Cam-lock in mandrel prevents slip July 7—137
Good tools, plus experience, make better gears Feb. 18—140
Interchangeable mandrels to cut hobbing costs May 12—138
Harding, H. V. & V. E. Matulaitis. Arc machining makes hard-to-cut jobs easy Mar. 3—116
Harkins, F. G. & H. C. Thompson. Novel methods are weld high-strength alloys Dec. 8—119
Harkins, Frank. Sigma welding stars on 3 new jobs Aug. 18—109
Harvest, Adolph. Metric threads cut without special gears Mar. 3—177
Pin pivots cross-slide for generating radii Apr. 28—129
Hatfield, George A. Recording voltmeter checks weld quality Apr. 14—158
Heatley, James. Turning a parabola Oct. 13—169
Heger, J. J. Why we now make better stainless steels Oct. 13—119
Hesse, C. W. Souped-up tooling does double-decker turning Jan. 7—141
Hicks, Robert G. Ceramics shield stainless for jets July 21— 99
Hill, Abram. Expansion tax Oct. 13—171
Hilton, G. W. & Thomas Shields. Dam tooling turns out tough steel rollers and tracks Nov. 24—130
Hoard, R. C. Emergency reamer practice Jan. 7—147
Hodge, Stanley. Planer fixture bends bolts Mar. 31—120
Hoffman, F. C. How to bend high-strength extruded shapes July 21—115-122
Hough, Miller. Adjustable press cutoff tool Jan. 7—152
Howe, Otto V. Carbide insert stops swing-stop wear Sept. 1—143
Pin holder grips screws June 9—164
Hsu, T. H. Bandsaw slotting fixture Sept. 1—143
Clamping die forms round springs July 21—137
No-scrap hinge die Dec. 22—124
Piece and draw in simple die Sept. 1—144
Rubber-backed dies form rocket-fin curves July 7—161
Rubber punch cuts lead foil Aug. 4—132
Three dies form 1-in. rings Aug. 4—133
Toothed stripper clears feeding strip Apr. 28—125
Hubbes, Walter. One basic card controls all tools Apr. 14—170
Hunsh, D. R. Re-scheduling flattens zig-zag production curve July 7—157
Hutchinson, E. F. & A. J. Rosenberg. How to weld titanium May 26— 93

ISETTS, ROGER. Spotfacer made from old drill June 9—163

JACOBS, F. C. Non-tangent radii on simple dresser Sept. 15—165
Jacbs, Hadley. Turret mirror saves steps in deep-hole boring May 12—176
Jaro, W. S. Reamer alignment counteracts table-indexing errors Feb. 18—166
Jeannet, Paul. Spindle adapter for lathe centers small size bars June 9—162
Jensen, A. V. Two-position drill table saves space, ups accuracy Aug. 18—114
Jewett, Jack. Off-center V-roller clamps odd-shaped part Mar. 3—179
Johnson, Arthur S. Off-the-job accidents cost $1 billion a year Oct. 13—148
Johnson, S. J. & P. R. Noling. How to estimate hobbing time Apr. 14—127
Johnstone, Richard T. Fiber ducts save steps in wiring machine panels Dec. 8—105
Jordan, Paul. Rebuilding a boring machine pays off Jan. 7—142
Surplus borer tooled for spheres Feb. 4—110
Judkins, M. F. Tool-shank sizes for carbides Feb. 18—268

KAISER, E. J. How to grind boring tools Pts. 1 & 2 Mar. 31—125
Kalb, C. W. "Strip" broaching boosts output Apr. 28—124
Kampe, William R. Ratio determines depth of thread chasing feed Dec. 8—143
Karcher, Leo F. Adjustable roller gage rides with stock May 26—124
Karfunkel, Max. Cutoff-tool holder has no overhang July 21—129
Hand-controllel shaper grinds cutters May 12—179
Kasper, L. Bracket locks without marring shaft July 21—127
Drilling opposed holes without interference Feb. 4—130
Keeleric, George & L. H. Metzger. Electrolytic grinding Nov. 10—154
Kelly, William H. Employing physically handicapped workers pays off Dec. 22—102
Kendall, R. V. Pipe taps electrically etched Apr. 28—129
Kerr, Craig. Ball grippers retain work on tapered turning mandrel July 7—160
Khoury, N. F. Expanding fixture grips round collars July 7—158
Offset drill spindle gets under shoulders June 9—165
Kilbourn, O. O. Cam-latch speeds steadyrest loading Sept. 15—166

(ed) Editorial (P.I.) Practical Ideas

King, J. W. & G. C. Matson. Four feeds automatize punch press Jan. 7—132
Kirk, Arthur F. Accurate sphere turner driven by leadscrew Feb. 18—168
Kreuger, R. Simple trick saves toolmaker's time Dec. 8—146
Kronenberg, Dr. Max. Make research data useful to the shop man Sept. 15—145
Reduce machine vibration Sept. 29—101
Krouch, D. K. Ceramics make furnace fixtures last longer July 21—101
Kusmer, Stanley. Grooving cutter uses carbide toolbits Dec. 8—146
Kuzmick, Jerome F. Hot molding increases scope of powder metallurgy July 7—132

LABROAD, E. J. How to design diamond pin locators Dec. 8—108
Lackner, Walter. Precision cutoff attachment Sept. 15—162
Laimbeck, Robert. Arbor collars assemble without disassembly Apr. 28—125
Double tool saves steel May 12—175
Ten shop tools do specialized operations Jan. 7—154
Welding clamps hold beams and irons May 12—177
LaLond, W. T. Signal light monitors air mechanisms Feb. 4—132
Lambert, Oscar F. Drill chuck drives taps Sept. 1—142
Simple mechanism increases gear-shaper capacity Sept. 1—140
Special tap for brass Oct. 27—148
Undiluted water-soluble coolant June 23—127
Landvater, J. H. Drill speed and feed charts Pts. 1, 2 & 3 Mar. 17—161
Larson, E. T. How to conserve diamond wheels Pts. 1 & 2 Feb. 4—173
Latter, Clyde H. "Cumulative sampling" boosts shop output 22% Sept. 29— 95
Laughner, E. M. Induction brazing can be used for copper and copper-alloy parts Nov. 24—135
Lee, C. Y. Double-duty jig for two drill jobs Mar. 3—180
Eccentric boring head Sept. 15—164
Homemade floating diehead Sept. 15—163
Line-boring tailstock Sept. 15—163
Precision tapping setup produces accurate nuts Feb. 4—131
Spring-winder attachment powered by lathe spindle Jan. 7—156
Tailstock attachment braces slender work Feb. 4—133
LeGrand, Rupert. Curtiss-Wright boosts output with machinability data Nov. 24—141
Dodge automates press forging Sept. 29—123
Grinding fixture aids die manufacture Nov. 24—134
How Ford automates production lines Mar. 17—135-150
How to keep ± 0.0002-in. accuracy throughout press operations May 12—132
Plasticale prototypes speed Ford tooling May 12—139-164
Timed press tools make and assemble three parts Feb. 4— 98
Lensky, Albert. Shear mechanism on die works every eleventh stroke May 26—121
Lettino, Fred. Checking noisy machinery July 21—127
Don't neglect feed volume for air operated devices Nov. 10—171
Flashlight on rule gets behind machinery July 21—128
Oil-absorbent spreader Oct. 13—170
Oil pan controls fluid quantity Sept. 1—140
Part counting stand Dec. 8—142
Levitt, Albert L. How to control coordinate tolerances Mar. 31—166
Levowich, Bernard. Counterbore for plastics Mar. 31—119
Lewis, W. Eccentric turning attachment Sept. 29—130
Lingenfelder, Fred H. Indicator gage checks machine dovetail Mar. 17—156
Linsley, H. E. How to run a drill press Feb. 18—147-162
How to run an engine lathe May 12—143-158
How to run a grinding machine Oct. 27—125-140
Lipowski, William. Outboard spindle bores oversize plate Jan. 7—155
Long, B. E. Jr. Avoid broken-drill trouble Nov. 24—160
Solid parallels on chuck Sept. 29—131
Loria, E. A., F. W. Boulger & H. L. Shaw. What constituents affect machinability of gray irons? Oct. 27—122
Lorimer, D. Chase acme threads in one lathe cut Oct. 27—147
Lovejoy, Stanley W. How and why taps are precision ground June 9—135-142
Luchr, Fred W. Trepanning speeds production of deep holes Mar. 31— 96
Lurz, Frederick C. Attachment feeds grinder on lathe Mar. 17—156
Combination toolholder gages cut-off lengths May 12—178
Eccentric-grinding equipment forms sewing-machine shafts Feb. 4—131
Indicating tapper cuts small threads Jan. 7—154
Slitting attachment works on miller table Feb. 18—167
Lyons, Martin A. Try this plan for industrial truck maintenance Aug. 4— 98

MAAS, LAWRENCE. Tanks roll on weld-ed wheels June 23—106
MacKinnon, C. D. Compound curve machined on boring mill May 26—122
Converted lathe bores ball sockets Aug. 18—131
Magee, J. C. Button block does precise hole locating July 21—129
Stop-jaw creep on cam-lock vise Sept.15—166
Mallory, John W. Super "nerve center" cam Mar. 31— 93
Manuele, Joseph. Increase machine capacity with control charts (charts) Feb. 18—131
Marsh, Roger. Chuck wrench keys lathe switch Feb. 4—130
Martin, C. L. Hand jig acts fast Jan. 7—153
Martinka, Rudy. Shims enlarge hole tools Apr. 14—177
Mate, Joseph. Emergency transfer screws Nov. 24—163
Matson, C. C. & J. W. King. Four feeds automatize punch press Jan. 7—132
Matsumoto, K. Clamping lathe dog acts quickly Jan. 7—152
Matulaitis, V. E. & H. V. Harding. Arc machining makes hard-to-cut jobs easy Mar. 3—136
McCafferty, John T. Internal thread guide Nov. 24—163
Pipe makes rugged boring bar Nov. 24—161
McCall, William W. Are you paying too much for insurance? June 23—104
Sorry you're not covered Nov. 24—158
McDonald, J. Gear-centering device locates shafts for boring May 26—123
McKenzie, M. M. Jackscrew die-lifter Sept. 1—142
McNeil, Daniel E. How to cut overhead costs Sept. 29—111
Menkin, B. Double-action die forms, pierces, pronged collets Nov. 10—174
Merchant, Eugene & Joe H. Crawford. High rake angles aid milling performance July 7—127
Merry, R. Cam for jig clamping Dec. 8—145
Constructing a tangent to a circle Feb. 18—169
Gravity bearings support idler gear July 21—127
Lever clamp eliminates half-turn screw Sept. 1—140
Shim gage checks taper May 12—177
Metter, Charles W. Before you improve materials handling, ask yourself is this trip necessary? June 9—143
Metzger, L. H. & George Keeleric. Electrolytic grinding Nov. 10—154
Meyer, Louis. Boring-bar brace allows quick adjustment Aug. 4—129
Miller, George T. Small DC motor runs lapping setup Aug. 18—131
Miller, L. G. Induction hardened gears show little distortion July 21—141
Miller, W. Curtis. Low-cost methods speed die construction Dec. 8— 93
Mills, Sherman. Headstock bar feed works on turret lathe June 9—163
Mishler, Ora F. & Fred D. Foreman. How Studebaker makes a crankshaft Mar. 3—156
Mitchell, R. Fawn. The collimator and how to use it Nov. 10—161
Montag, Mordechai. Quick-acting beams compass Oct. 27—146
Moran, M. Multi-purpose toolholder Nov. 24—164
Morgan, H. Cam-controlled punch forms accurate tube Sept. 29—131
Guide-strip takeup counteracts width variations Mar. 31—121
Remote light source aids radial drill June 23—126
Short-run dies are soldered together Feb. 18—168
Trouble shooting die maker Dec. 8—144
Morrison, R. W. Four jaws work fast as three Sept. 1—142
Motherwell, George W. Hollow extruded forgings conserve critical materials June 9—119
Multberg, H. M. & A. E. Fristedt. Traversing friction meter checks carriage motion June 9—162
Murphy, J. J. How to shear to closer limits May 26—102
Murro, Haim. Adjustable clamp works with leaves Apr. 28—128
Centering device uses torsion spring Nov. 10—171
Grinder safety brake Sept. 15—164
Half-spheres measure hole center-distance Sept. 29—131
Rod collects punched blanks Nov. 10—173
Straightening wire Apr. 14—177
Stretching electric resistance coils Nov. 24—164
Workholding endmill Oct. 13—171
Myers, Philip E. Off-center pins mark center-distances June 23—124

NATHASON, M. JORDAN. How to seal porous castings Pts. 1 & 2 Jan. 7—161
Nelson, Carlton G. Scribing small shafts Jan. 7—153
Nelson, Oscar. Plow mold boards press-formed to shape June 9—122
Nicotera, Ernest T. & Harold Bernstein. Open die forges titanium cones Feb. 18—136
Noling, P. R. & S. J. Johnson. How to estimate hobbing time Apr. 14—127
Nolle, D. G. Body-controlled welding fixture Sept. 1—144
Shell-chucking fixture speeds turning operations Apr. 28—125
Nordhoff, W. A. 6 "shop kinks" boost output at Douglas Aircraft Aug. 4—108
Nystrom, William T. Air may solve your gaging problem Aug. 18—103

OBRESKI, JOHN. How flame and induction heating work Jan. 7—122
Olesen, Anker. Shaped driver speeds lathe loading Dec. 23—122
Olun, Dirck & Dr. Hugh N. Dyer. Wet belt grinding speeds production of extruded cylindrical stock Dec. 8—106
Opanowicz, Harry H. Adjustable holder for "last-word" indicator Dec. 8—143
Opanowicz, P. Old micrometer makes height gage Apr. 14—179
Vernier-action improves height gage Apr. 28—126
Orr, Dale. Antifriction steadyrest jaws Sept. 1—143

PALMER, N. Braced drill cuts at high speed May 12—176
Controlling grinding-wheel dust Nov. 24—161
Grinding centers for hardened parts Dec. 8—145
Grinding shaving tools on an optical grinder Nov. 24—160
Non-standard threading dies Nov. 24—162
Simple clamps speed tooling Oct. 27—144
Simple, rugged index plate does universal holding jobs Aug. 18—134
Small carbide boring bits work better than large ones June 23—128
Two chucking faceplates hold work on center June 23—125
Two equalizing locating methods May 26—121
Vise gage locates part for clean-up Aug. 4—134
Wood stock tubes cut shop noise Aug. 4—130
Paquette, E. F. Automation triples pail-line output Dec. 22— 98
Peacock, Ian J. Grinding wheel on lathe trems up chuck jaw Mar. 3—178
Saddle feeding lever speeds bench lathe Aug. 4—132
Spring headstock center increases shoulder-dering accuracy May 26—123
Tailstock handwheel locks quickly May 26—121
Pearson, S. N. Hinge clamp grips side of work Feb. 4—133
Pneumatic angle drill cuts bearing grooves Mar. 31—120
Pech, Lester J. Scribing circles on castings Apr. 14—180
Pecnka, Joseph A. Broaching makes an anchor Apr. 14—140
Perry, W. L. Crane and sling change chucks Apr. 28—128
Peterson, David C. Full conveyorization eliminates manual chip handling Oct. 13—162
Shock-absorbing flatter handle Dec. 22—123
Pflug, W. & A. J. Fischer. Preformed shapes save time and carbide Apr. 28—104
Phillips, S. Dale. Smart tooling solves tough elliptical boring job Dec. 8—140
Pigott, R. J. S. Little high-pressure jets from below cool cutting edges better Jan. 21—281
Pittella, Leo A. Scissors gage measures hidden diameters Oct. 13—171
Poole, A. H. Magnets find balance on flywheels July 21—127
Porsch, J. H. Calculating form tools Mar. 3—145-152
Powell, Howard. Triple electrode spotwelds wire guard June 9—151

RAINES, CHARLES C. Nut makes tap handle Feb. 18—169
Ramirez, Justo P. Radial drill turns large rings with remote power June 9—162
Spider honing cutter finishes diesel sleeves Jan. 7—155
Rawling, Ralph E. Pin measurement tables for involute gears Pts. 1 &2 June 23—133
Pts. 3, 4 & 5 July 7—163
Pts. 6, 7 & 8 July 21—133
Pts. 9 & 10 Aug. 4—137
Redl, Pablo. Bonus for not working Sept. 29—131
Old valves do odd machine-shop jobs Feb. 4—131
Portable-drill motor subs for gear motor Jan. 7—156
Punch table simplifies notching Mar. 17—155
Quick-sling lifts vertical tanks Sept. 29—133
Roll-on platform scale Sept. 29—132
Reed, A. V. & Norman Tweddle. Great grandpa did contour turning Nov. 10—119
Renson, A. T. Fulcrum fixture on mill cuts large radius June 23—127
Shaper swivel and tool cut radii and curves May 12—180
Richards, John T. How to work with beryllium-copper strip Mar. 31—99-114
Richter, William. Coil-winder speed nut has lever control Apr. 14—178
Rieske, Franklin. Precision lathe feed uses compound angle July 21—129

(ed) Editorial (P.I.) Practical Ideas

Ringquist, C. L. How to cool oil-quench tanks Aug. 18—106
Robert, Joseph J. How to machine stainless steel with carbides Oct. 27—109
Roberts, Robert P. Air and ideas make spot-welder automatic Dec. 22—104
Roberts, T. J. Profile gages finished on internal grinder Mar. 31—118
Roedder, Robert. Drillpress fixture has chuck on table Feb. 18—167
Wide index plate finger compensates for cutter width July 7—159
Rogers, Bernard A. Don't scrap HSS Jan. 7—152
How to cut gears without a dividing head Apr. 28—126
Special broached collet holds two stocks July 21—130
Rogers, D. A. Stenciling attachment works on screw machine Mar. 3—179
Vise hold-down Oct. 13—172
Rosenberg, A. J. & E. F. Hutchinson. How to weld titanium May 26—93
Rossi, Ralph J. Bridged templet guides radius-cutting planer Apr. 14—177
Simple tool cuts hidden chamfer Dec. 8—145
Rowan, Miles J. Chip conveyor cut job-shop downtime Feb. 4—104
How Ford extends automaticity to engine handling June 23—113-120
How Ford plans for low-cost chip handling Apr. 14—134
Latest improvements in press automation at Ford Dec. 8—109
Plant-wide planning stretches new-equipment dollars Mar. 17—119
"Shop in stockroom" provides point-of-use storage Feb. 4—124
Special duplicators speed experimental jet-engine blades Mar. 3—166
Tricky tooling stamps on stamping costs Feb. 18—138
Rudorf, Signed K. Holding blocks do a tough fixturing job Jan. 7—150
Rybarczyk, T. M. Multiple bending multiple production Feb. 4—100

ST. CLAIR, LEO J. How to tip tools with prehardened HSS Jan. 7—133-140
Salinas, J. C. Adjustable boring bar swivels on setscrews Mar. 3—176
Centerdrilling setup on turret lathe Mar. 31—119
Grease-gun pump Mar. 31—120
Six-station table is easily built Mar. 17—157
Slowing up air-cylinder action Mar. 3—180
Turret chip breaker clamps next to tool Mar. 31—122
Salmons, A. E. HSS form tools salvaged by regrinding July 21—130
Sanford, Albert C. How round is round? Nov. 10—124
Sanford, Jerry. How wing skins for B-47 stratojets are taper-milled Apr. 14—166
Sauer, Walter A. Stop scriber-pad loss Oct. 13—172
Schryver, L. E. End-mill fixture gages for grinding Apr. 28—127
Schub, A. F. How to roll back forming costs Mar. 17—152
Schwartz, Charles. Bandsaw storage rack made for 2x4's July 7—161
End-mill gage checks clearance angles Aug. 4—131
Scrap ejector for trimming dies Sept. 29—134
Seed, M. G. Britain, too, has electric-spark machining Nov. 10—159
Senter, Frank G. Gundrills are home grown at Allison Sept. 1—110
Shaw, H. L., E. A. Loria & F. W. Boulger. What constituents affect machinability of gray irons? Oct. 27—122
Shear, Fred. How Freiden applies solid-film lubricants Sept. 29—128
Shefelton, W. F. Peroxide tanks pose welding problems Apr. 14—173
Sheppard, George H. Band tool slotting Feb. 4—109
Shepperack, Joseph E. Ball-bearing stock guide Sept. 15—163
Shields, Thomas & G. W. Hilton. Dam tooling turns out tough steel rollers and tracks Nov. 24—136
Shum, John. Flame-fluxing brazes high-strength assemblies Nov. 24—133
Silvagi, J. & Vic Francis. Pin measurement of face gears Pts. 1, 2 & 3 May 12—183
Simpson, George L. Discourage corrosion through dry air June 9—127
Smith, Leonard T. Rubber roller clears saw chips July 21—128
Surface grinder from bench drillpress Oct. 13—168
Sorenson, Chris. Drill jig eases square-hole broaching Feb. 18—170
Sorenson, James. Measurement of case depth Mar. 31—129
Spencer, L. F., G. J. Stevens & V. Bankoski. How to machine and finish stainless steel Aug. 4—111-126
Spotts, Prof. M. F. Machining angles on the shaper Jan. 7—159
Springthrope, E. Die forms recess in drawn steel pot July 7—160
Starr, John. Hot dimpling forms tough aircraft skin Mar. 3—160
Steffey, Lott. Bus-duct production goes to town Sept. 29—105
Stevens, G. J., V. Bankoski & L. F. Spencer. How to machine and finish stainless steel Aug. 4—111-126
Stevens, T. F. & J. Dietlin. Radial spacing beyond normal jig-borer limits Dec. 22—123
Stewart, John. Boring internal clearance Oct. 13—172
Circular index table Oct. 27—147
High-speed lathe setup cuts interrupted helixes May 26—124
Stirrat, R. W. Slot-checking gage has dial indicator Feb. 4—133
Stocker, William M. Jr. Compound dies blank, pierce, and form multiple parts July 21—104
How aluminum bonding is keyed to production July 21—108
How modern gun-drilling improves bore-making May 26—109-116
Sprayed vapor ups tap life and speed Jan. 7—121
Storchheim, Samuel. How draw speed affects stainless wire July 21—124
How to electro-polish stainless steel May 12—141
How to understand brass Oct. 13—151
Strasser, Federico. Correction stop for blanking die Dec. 22—122
Die-filling jaws hold taper accuracy Mar. 3—179
Diemakers kinks Mar. 3—144, Mar. 17—153 Mar. 31—86, Apr. 14—131, Apr. 28—99, May 26—97, June 9—154, June 23—109, Aug 18—111, Sept. 1—115, Oct. 13—127, Dec. 22—103
Double blanking forms sharp teeth in press job July 7—160
File does emergency knurling Apr. 28—127
Follow these 22 steps in die setting Oct. 13—128
Maintain alignment in small sectional dies Dec. 8—143
Minimum slug clearance prevents jams Mar. 17—155
Piercing die for heavy stock Dec. 22—120
Sectional dies simplify machining May 12—179
Soluble oil lubricates punches May 12—178
Watch your language for presswork Sept. 1—136
Will symbols for press tools simplify communications? (chart) Sept. 1—135

TANGERMAN, E. J. Alco tooling assembles the M-47 hybrid Aug. 18—119-126
Automatic roll of the line Sept. 15—137
Carbide bur at 90,000 rpm finishes exact R63 bores Mar. 3—142
CO_2 cools tools Mar. 3—129
Dynamometers change art to science Nov. 10—130
Europe studies carbide cutting Feb. 18—134
How Sperry harnesses the electron Apr. 14—143-157
Tangerman, E. J. & George H. De Groat. Men of "parts" watch machines work at Sylvania Sept. 15—113-136
Tricky tooling turns out tubes June 23—97
Tarasov, Dr. Leo P. How to grind titanium Nov. 10—155
Taylor, S. Drilling tiny holes Oct. 27—145
Lathe saddle works like turret July 21—130
Tedds, D. F. B. Skilled investment casting July 7—141
Thompson, H. C. & F. G. Harkins. Novel methods are weld high-strength alloys Dec. 8—119
Thomson, J. A. Simple zinc-alloy dies speed small orders July 7—138
Thuma, Richard F. Gate guards give greater press safety July 7—130
Thurston, Robert T., John Wulff & James E. Cline. Spray and sinter to make high temperature alloy parts Mar. 17—172
Tilles, S. What clamping force June 23—131
Tomicki, John T. & C. Richard Gunzer. Plan your government contracts for profits Jan. 21—298
Tour, Sam. Sub-zero hand-tool failures suggest new steels and treatments Nov. 24—154
Trail, Thomas. Drill gage always ready Sept. 29—133
Drillpress safety plug and chuck wrench Feb. 18—167
Hacksaw blade saver Oct. 13—169
Safety signal for hoist control Nov. 10—174
Tweddle, Norman & A. V. Reed. Great Grandpa did contour turning Nov. 10—119

UNWIN, D. J. Vertical milling attachment does light, accurate work Apr. 28—130

VANCE, DONALD L. Hand bending tools make roller-bearing brackets Apr. 28—128
Van Cutsem, Albert T. Functional tooling with unit air-operated drills June 9—124
Van Hecke, George J. Boring tools made from old drills, reamers Mar. 17—157
Vare, R. G. Compound angles simplified Feb. 4—133
Copper strips spotweld stainless Apr. 14—176
Geared shafts milled in pairs July 7—161
Multi-jaw chuck adapted for holding odd shapes Mar. 17—158
Shear for press tools Nov. 10—171
Simple sine bar sets grinding angles July 7—162
Sine bar with lever corrects compound angles Mar. 17—155
Spotweld spacing Sept. 1—142
Springs lead cutter that follow templet June 9—161
Super sine bar does multiple work Aug. 4—131
Tube-conected elbows level large fixtures Mar. 31—121
Welding thin plates Nov. 10—173
Vetsch, A. Anvil bush centers measuring rods June 23—125
Boring-bar hole gage centers automatically Apr. 14—179
Differential threads—discussion Mar. 3—177
Drilling holes for rough broaching Nov. 10—120
Electrode removes broken parts from deep holes Nov. 10—172
Inverted countersink Sept. 1—141
Keyway tools added to regular broaches Jan. 7—153
Only two operations to form ring cut Nov. 10—172
Simplified arbor collars July 21—127
Victory, Frederick C. Precision contour grinding makes better tools Pt. 1 Sept. 15—154
Pt. 2 Sept. 29—106
Vinger, Lyle. Offset boring tool rotates to cut Nov. 10—161
Volkmar, W. H. Automatic welding makes eyebolts faster, better Aug. 18—127
Von Hambach, E. Nerve and sharp tools machine any stainless at high speeds Jan. 7—117
Von Ludwig, Davidlee & Rawson L. Wood. Investment castings need not be "free-machining" stainless Nov. 10—147
Voss, Hermann. Washer punch Sept. 15—165

WAGNER, H. W. Cost of grinding carbide (Ref. Bk Sheets) Apr. 14—183
Walker, Edward. Double equalizing clamp grips twin parts Aug. 4—133
Graphite blocks trepanned to save $20 each Nov. 10—122
Swivelling clamp arm has fast action Mar. 31—118
Ward, Alwyn. Welding clamps locate and grip May 12—178
Warner, Eugene P. What about Tito? July 7—178
Watkins, E. R. & J. M. Case. How Oak Ridge machines beryllium Dec. 22—93
Watson, Donald. Drillpress adapter inverts rivet heads Aug. 18—133
Simple fixture turns many radii Dec. 22—121
Wein, Samuel. How to apply metal to glass and ceramics July 7—147-154
Welch, C. F. Lathe and powered faceplate make versatile T-lathe Feb. 18—166
Wenke, Gerhard. Vertical miller cuts half sphere Feb. 4—130
Whitman, W. Theodore. Hand grinder attaches to surface grinder Aug. 18—133
Wigton, W. B. & J. L. Dutcher. Contouring with heavy machine tools Oct. 27—114
Willey, C. H. Flat bar clamps versatile work holders Dec. 22—122
Williams, H. O. Sonic tester checks bonding of honeycomb panels Sept. 1—116
Williams, L. B. Making special cutters for odd milling jobs Aug. 4—133
Wilmus, Pierre. Hole punch for thin-walled tubing Dec. 22—121
Tailstock center for old lathe is spring-loaded Mar. 17—158
Wilson, Frank E. Nibbling die slides away from high costs Aug. 18—129
Wiltrakis, Joseph E. Better handling saves building space Dec. 8—136
Winburn, Raymond K. Tool sharpener does odd shop jobs June 9—165
Winkler, E. How to mill a large radius Oct. 13—170
Progressive radius milled by key-shaft guided cutter Nov. 10—170
Winston, Sam. Bench micrometer checks slots and holes June 23—126
Edge locating block speeds jig-borer set-up Dec. 22—122
Setup block works on lathe or grinder July 21—129
Woerle, H. Ball-bearing tube center Oct. 27—145
Woerle, J. Simple connection powers tailstock Mar. 31—118
Wood, M. Sgt. James K. Expanding mandrel works with chuck Aug. 4—134
Wood, Rawson L. & Davidlee Von Ludwig. Investment castings need not be "free-machining" stainless Nov. 10—147
Worth, S. V. Make shear pins shear On Tightening hidden bolts Oct. 13—170
Wright E. A. C. Double level aligns portable drill Apr. 28—129
Wril, John J. O. Plastic threads cut by grinding Mar. 3—178
Wulff, John, James E. Cline & Robert T. Thurston. Spray and sinter to make high temperature alloy parts Mar. 17—172

ZOOK, ELMER. Pipe threads Pts. 1, 2 & 3 Nov. 10—177
Pts. 4, 5 & 6 Nov. 24—167
Zuerl, Donald. Inclined jack pin registers press stock Apr. 14—176

(ed) Editorial (P.I.) Practical Ideas